

Classification:

EL15-015

Reference:

ITB15-023

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

June 12, 2015

2016 INFINITI; REGISTRATION OF NEW I-KEYS WHEN ORIGINALS ARE MISSING

APPLIED VEHICLES: 2016 QX60 (L50)
2016 QX60 Hybrid (L50)
2016 Q50 (V37)
2016 Q50 Hybrid (V37)

SERVICE INFORMATION

When replacing both of the vehicle's I-Keys, due to being lost prior to vehicle delivery, new I-Keys can now be registered **without the BCM (or ECM) being replaced.**

Do not replace the BCM (or ECM) before replacing I-Keys for the Applied Vehicles.

To register keys:

1. Push the Extended Storage Switch (ESS) in.
2. Press the push start button to wake up BCM.
3. Turn ON the hazard to keep BCM in wake up mode.
4. Plug in CONSULT-III plus (C-III plus).
5. Register Intelligent-Keys using C-III plus.

IMPORTANT: For those vehicles that are being retained in inventory after the keys are replaced, pull out the ESS to return the vehicle to Extended Storage Mode.

CLAIMS INFORMATION

Note that lost items are the responsibility of the dealer, and are excluded from the applicable Warranty; please consult the "Infiniti Warranty Information Booklet" for specific details.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.