



SERVICE BULLETIN

Classification:	Reference:	Date:
BT15-027	NTB15-092	October 23, 2015

2015 MURANO; CENTER SPEAKER GRILLE SERVICE INFORMATION

APPLIED VEHICLE: 2015 Murano (Z52) with BOSE® audio system

APPLIED VIN/ DATE: Vehicles built on or after 5N1AZ2M(* *)FN 249337 and June 20, 2015

SERVICE INFORMATION

BOSE® audio systems are found in 2015 Murano Platinum, SL, and SV models equipped with the Premium Package only. Center speaker grilles on 2015 Murano vehicles equipped with a BOSE® audio system **built after and starting with** the VIN and date shown above do not have a BOSE emblem.

Do not replace a center speaker grille* under warranty because it does not have a BOSE emblem. Replacement of this part for this reason on this model is not covered under warranty.

- See the next page for further detail.

** If the 2015 Murano Platinum, SL, or SV vehicle with Premium Package was built after and starting with the VIN and date shown above.*

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.




Figure 1

- ① 2015 Murano Platinum, SL, and SV models equipped with the Premium Package (only) **built before** VIN and date 5N1AZ2M(**)FN 249337 and June 20, 2015 have a BOSE emblem.
- ② **ALL** 2015 Murano models **built after and starting with** VIN and date 5N1AZ2M(**)FN 249337 and June 20, 2015 do not have a BOSE emblem.



Figure 2




Figure 3