

Classification:

BT15-035

Reference:

ITB16-001

Date:

January 4, 2016

## 2015 QX60; TIE DOWN HOOK NO LONGER STANDARD

<b>APPLIED VEHICLES:</b>	2015 QX60 (L50) 2015 QX60 Hybrid (L50)
<b>APPLIED VIN &amp; DATE:</b>	2015 QX60: Vehicles built after 5N1AL0M(**)FC 559658 // December 15, 2015 2015 QX60 Hybrid: Vehicles built after 5N1CL0M(**)FC 559665 // December 15, 2015

### SERVICE INFORMATION

- The tie down hook is no longer included with the jacking tools on 2015 QX60 vehicles, effective with the Applied Date and VIN shown above.
- Do not submit warranty claims for a missing tie down hook (a hook that was not originally supplied with the vehicle).




Figure 1

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.