

Classification:

RS16-004

Reference:

ITB16-016

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

April 22, 2016

OCCUPANT CLASSIFICATION SYSTEM LIGHT OPERATION LOGIC CHANGE

APPLIED VEHICLES: 2016 QX60 (L50)
 2016 QX60 Hybrid (L50)
 2016 Q50 (V37)
 2016 Q50 Hybrid (V37)

APPLIED DATE: 2016 QX60 built after March 31, 2016
 2016 QX60 Hybrid built after March 31, 2016
 2016 Q50 built after March 27, 2016
 2016 Q50 Hybrid built after March 27, 2016

SERVICE INFORMATION

Infiniti is issuing this Technical Service Bulletin to clarify that a change has been made for the logic that controls the Occupant Classification System (OCS) and "passenger airbag indicator" (PABI), as described in the Owner's Manual. This TSB applies only to vehicles using the 2-sensor OCS.

Those changes are:

- PABI light is ON with an empty front passenger seat.

The following table below illustrates when the PABI illuminates with the logic change.

CONDITION	DESCRIPTION	PASSENGER AIR BAG INDICATOR LIGHT	FRONT PASSENGER AIR BAG STATUS
Empty	Empty front passenger seat	ON (illuminated)	INHIBITED
Nobody/Somebody	Bag or Child or Child Restraint or Small Adult in the front passenger seat	ON (illuminated)	INHIBITED
Adult	Adult in front passenger seat	OFF (dark)	ACTIVATED

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.