



Preliminary Information

PIP5654A 10L90 10L80 10L60 10 Speed Automatic Transmission Valve Body Part Unique Number PUN May Contain the Letter O Or The Number 0

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2020 - 2021	All	All	L3B	MQA
Cadillac	CT5	2020 - 2021	All	All	LGX LSY	MHS
Cadillac	CT6	2019 - 2020	All	All	LGX LTA	MHS MHW
Cadillac	Escalade Models	2018 - 2021	All	All	L86 L87 LM2	MF6 MQC
Chevrolet	Camaro	2017 - 2021	All	All	LGX LT1 LT4	MF6 MGL MI1 MI2 MI4
Chevrolet	Silverado 1500 New Model	2019	All	All	L87	MQB
Chevrolet	Silverado 1500	2020 - 2021	All	All	L84 L87 LM2	MQB
Chevrolet	Suburban RST	2019 - 2021	All	All	L84 L86 L87 LM2	MF6 MQC
Chevrolet	Tahoe RST	2018 - 2021	All	All	L84 L86 L87 LM2	MF6 MQC
GMC	Sierra 1500 New Model	2019	All	All	L87	MQB
GMC	Sierra 1500	2020 - 2021	All	All	L84 L87 LM2	MQB
GMC	Yukon Denali Models	2018 - 2021	All	All	L84 L86 L87 LM2	MF6 MQC


Involved Region or Country	North America
Condition	Some customers may comment on the operation or performance of the 10L80 or 10L90 transmission.
Cause	Technician's may replace the valve body to address these concerns.

Correction:

If the valve body is replaced the dealer technician may find that software may not accept the Part Unique Number (PUN) during the characterization procedure.

Please be aware that the PUN may contain the letter O or the number 0 as shown in the picture below.

Note: The letter O may be found in other locations than shown below.



Call Out 1

The number 0.

Call out 2

The letter O.

Version History

Version	1
Modified	06/13/2019 - Created on. 04/09/2021 - Added the 2020 and 2021 model years. Added the 2020-2021 Cadillac CT4 and CT5 models.



© 2021 General Motors. All Rights Reserved.