



Mitsubishi Motors North America, Inc.

6400 Katella Avenue
Cypress, CA 90630
Tel: 714-372-6000
www.mitsubishicars.com

March 7, 2016

Associate Administrator
National Highway Traffic Safety Administration
1200 New Jersey Ave SE
Washington, D.C. 20590

Mitsubishi Motors North America, Inc. (MMNA) submits this letter in accordance with 49 CFR Part 579.5 "Notices, bulletins, customer satisfaction campaigns, consumer advisories, and other communications." Enclosed is a copy of applicable instructions or explanations sent during the month of February, 2016 to owners, dealers, and/or purchasers of motor vehicles or equipment sold by MMNA.

- 54-MG-01-16: SRS Connector Corrosion – Safety Recall Campaign
- ATIN-16-SC-001-A: ECM Reprogramming for Engine Knocking Noise – Service Campaign
- SC-16-001: ECM Reprogramming for Engine Knocking Noise – Service Campaign
- TSB-16-52A-001: Front Seat Slide Rails - Lock Position Timing Not Synchronized
- TIN-16-00-001: Electrical Insulation Gloves
- ATIN-16-SC-001-B: ECM Reprogramming for Engine Knocking Noise – Service Campaign – Customer Letters
- SC-16-001 Customer Letter_US

If you have any questions, please contact me at one of the contact points below during normal business hours Pacific Time.

Sincerely,

A handwritten signature in black ink that reads "Melinda Borisenko".

Melinda Borisenko
Specialist, Technical Publications
MBorisenko@mmsa.com
Phone: 714-372-6210

