

ROCKET 3 INSTRUMENT CALIBRATION DOWNLOADS



Notice Information

Ref	18186
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CA) – April 9, 2021

TOL Ref. # 18186-SVC

ROCKET 3 INSTRUMENT CALIBRATION DOWNLOADS

As of TDT version 2021-06, there are now 2 options for Rocket 3 instrument calibrations. When updating the instruments, you must select between 'standard' and 'accessory' calibrations:

Standard Calibrations: For use on Rocket 3 models with OE indicators fitted

Accessory Calibrations: For use on Rocket 3 models with accessory scrolling indicators fitted

Caution: Using the incorrect instrument calibration for the indicators fitted may lead to incorrect indicator functionality and permanent damage to the indicators.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.