


TECHNICAL TOPICS

POWERTRAIN



<p>Check Engine MIL</p>	<p>19MY – Onward Discovery Sport, RR Evoque, RR Velar, Defender, RR/RR Sport PHEV, XE, XF, F PACE, F TYPE, E PACE equipped with AJ20P4</p>
<p><u>Customer Complaint:</u></p> <ul style="list-style-type: none"> – Check Engine MIL is illuminated. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> – DTC P0096-85 is stored in the PCM. – DTC P0099-00 may also be stored in the PCM. <p><u>Status:</u></p> <ul style="list-style-type: none"> – This condition is currently under investigation. – Engineering is seeking data and parts from an affected vehicle undisturbed. – Raise a TA prior to performing diagnostics on the vehicle and reference the SSM so the TA can be escalated directly to Engineering for support. – Reference SSM 75405/75406. 	



PRINTED COPIES ARE UNCONTROLLED