

WMC3 Workshop campaign - Replacing hydraulic unit

Version 1

WMC3 Workshop campaign - Replacing hydraulic unit

Overview

Due to a temporary manufacturing problem, there is a possibility that the installed hydraulic unit for the brake system was not manufactured according to specifications in the affected vehicles.

If this is the case, this can result in noises from the hydraulic unit in the engine compartment area over the service life of the vehicle.

To prevent this from happening, the hydraulic unit in the affected vehicles must be replaced.

Within the market area for which you are responsible, please arrange for this measure to be carried out on the affected vehicles immediately.

Model type	Macan (95B)
Model year	2020-2021
Number	6

Parts required

Part No.	Designation	Quantity/vehicle	Parts return*
95B614511T	Hydraulic unit (I-no. 8T6)	1 unit	No
95B614512T	Hydraulic unit (I-no. 8T3)	1 unit	No
00004321082	Brake fluid	2 units	No

* The parts must be stored until such time as the **related warranty or campaign claim has been credited**. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Ordering required parts

Please order the required parts as necessary. A PRMS ticket to PCNA Parts Support with VIN will be required to order this part.

Warranty processing

Scope 1: Only relevant for vehicles without ACC (I-no. 8T6)

Damage Code	WMC3 66 000
Repair Code	2
Working time	164 TU

Scope 2: Only relevant for vehicles with ACC (I-no. 8T3)

Damage Code	WMC3 66 000
Repair Code	2
Working time	164 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Porsche Mobility

If requested, the mobility of the affected customer can be assured by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

Further information

Work instruction	TI No. 51/21, Group 4, Service, WMC3
Vehicle list and allocation	See PCSS or attached VIN list for reference
Technical Information*	See PCSS, Aftersales Document Database or attached TI for reference

[WMC3_TI_95B_EN.pdf](#) ⓘ

140.7 KB

(22 views)

[WMC3 VIN List.xlsx](#) ⓘ

8.5 KB

(78 views)

Created by [Ryan Cooney](#) on Jul 30, 2021 3:52 PM. Last modified by [Ryan Cooney](#) on Jul 30, 2021 3:57 PM.

Categories: Workshop Campaigns, Macan

Tags : [macan](#), [workshop](#), [year m](#), [wmc3](#)

484 Views

[Report Abuse](#)

Content and Topics

Personal

Manage

Create

Your Groups >

Edit Profile >

Admin Console >

Discussion >

Your Content >

Change Password >

PPN Administration >

Files >

Your Places >

Document >

Collaboration >

Document

Blog Post >

Poll >

Event >

Photo Album >

Idea >

Space >

Group >

© 2021 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [010](#)