

Reference	SSM75526
Models	I-PACE / X590
Title	I-Pace (X590) 19-21MY - Rear Wheel Arch Liner Appearance Incorrect
Category	Body
Last modified	09-Sep-2021 00:00:00
Symptom	108000 Ext. Trim/Accessories
Attachments	WAL SSM Attachment.pdf (WAL SSM Attachment.pdf)

Content **Issue:**
A customer reports either of the rear wheel arch liners appear to have dropped down and in some cases the liner has come into contact with the rear tire/ wheel, causing a noise when the vehicle is in motion.

Cause:
There is a gap (see image 1 in the attachment), the gap highlighted (red box) allows water, mud or other debris material to enter and build up between the liner and vehicle body. The increase in weight can cause the liner retaining clip to come away from the body, leading to the wheel liner to drop down and come into contact with the rear wheel/ tire.

Action:

Parts Required;

- JDE12870 – Push Pin (Clip), 2 required for each wheel liner repair
- New wheel arch liner (If the liner has been damaged due to coming into contact with the rear wheel, please search for the part number in JLR Electronic Parts Catalogue (EPC))

Action;

1. Remove the affected wheel arch liner (WAL), following the topix procedure (501-08: Exterior Trim and Ornamentation > Removal and Installation > Rear Wheel Arch Liner)
2. Inspect the WAL, if it has come into contact with the rear wheel/ tire, please replace the liner
3. Remove any dirt/ debris from the wheel arch body surfaces
4. Trim the area shown using a straight edge and a knife/ scissors, to remove a strip of the WAL as highlighted in slide 2 of the attachment
5. As highlighted in slide 3 of the attachment, place the strip over the gap at the top of the wheel arch liner and drill two 8mm holes and fit the push pin clips securing the strip to the wheel arch liner (See slide 4)
6. Refit the affected wheel arch liner (WAL), following the topix procedure (501-08: Exterior Trim and Ornamentation > Removal and Installation > Rear Wheel Arch Liner)

Thank you in advance for your assistance with this matter.

anBhdHRlcnM7MjAyMS0wOS0xM1QxMjowNzo0MS41MDRaOzEzNi4yMjYyNDguODE7