

## CAMPAIGN LAUNCH STATUS

### N614 & H367 UPDATE PRIOR TO SALE – POWER STEERING



#### H367 UPS7921 JAGUAR AND N614 UPS 8021 LAND ROVER - LOSS OF STEERING ASSISTANCE

AFFECTED MODELS	21MY RR Evoque, Discovery Sport and E-PACE
VOLUME AFFECTED	852 USA 78 CAN
ISSUE/REPAIR	Affected vehicles may experience a loss of steering assistance, with a 'Steering Assistance Reduced' message, along with other related messages, displayed on the instrument cluster. The steering assistance will drop to 50% for 10 seconds and then 0% but after the ignition is cycled the steering assistance and related features will return to normal.. Vehicles will receive a power steering control module software update.
REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	September 27 <sup>th</sup> , 2021
Notes	Retailer stock Oct 12th 2021, 508 USA 45 Canada.



PRINTED COPIES ARE UNCONTROLLED