10/29/21, 12:16 PM Article



Lighting Control Module (LCM) Replacement - Refer To Technical Parts Information (TPI) 364 -**034 Control Unit**



> Internal Content

For more information refer to TPI 364 - 034 Control Unit, found in the Trucks Dealer Portal under the Service Tab - Impact - Parts - Parts Catalog - TPI.



k22634733		us04	us07	us10	us10)+obd13
us14	us1	4+obd15	us14+obd16		us14 cng	
us17	us1	us17+obd16		vnm	vnx	vah
vhd	vt	d12	13l engine		mack	volvo

Related links and attachments

No links or attachments available



Give feedback

to help improve the content of this article

IMPACT 4.07.113 10/29/2021

TPI 364-034, Control Unit

When replacing device P/Ns 20744283, 20514900, and 20427169 you must run conversion kit P/N 85115541 as an accessory kit using the diagnostics tool.

Copyright to this documentation belongs to the Volvo Group. No reproduction, copying, change, amendment or other similar disposal is entitled without prior written consent by the Volvo Group