



Volvo Chassis - With 2018 New Style Instrument Cluster - Radio Mutes When In Reverse - Model Years 2018 And Newer



> Internal Content

If an applicable vehicle presents with the issue described above:

- Update the Instrument Cluster software to the current version, released the week of December 8 2019.
- Verify proper operation.



Tags

[k55899505](#)

[volvo](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article