



Inactive Code P25AE00 Being Generated After A Hard Pull And A Momentary Drop In Engine Oil Pressure (Low Oil Pressure) (Possible Related Codes - SPN 4811 , SPN 100 , PID 100)



> Internal Content

If no other faults have been logged, Engine Oil Temperature should be verified with a heat gun and the values compared with the sensor readings via sensor monitoring in Guided Diagnostics.

Once all diagnostics have been performed and the Engine Oil Temperature Sensor has been determined to be faulty replace it confirming it has resolved the issue.

If it is found to be without fault and is accurate in the Engine Oil Temperature value information it is relaying, please contact Technical Support Services and start a case documenting all code information and current diagnostic results.

Tags

- [k13242100](#)
- [p25ae-00](#)
- [spn 100](#)
- [spn 100 fmi 1](#)
- [spn 4811](#)
- [spn 4811 fmi 2](#)
- [spn 4811 fmi 1](#)
- [mid 128 pid 100 fmi 1](#)
- [p25ae00](#)
- [mack](#)
- [volvo](#)

Related links and attachments

Live UI links or attachments available



[Give feedback](#)

to help improve the content of this article