



Dynamometer Testing On 2016-17 Volvo Chassis



> **Internal Content**

Vehicles built after May 21, 2016 equipped with a 13Liter engine will exhibit severe low power results on a dynamometer if parameter CVU is set to 2. Parameter CVU is located in the Light Control Module (LCM) MID 216.

Two options that can be performed in order to bypass this option for testing:

- Set CVU to 0 (this setting will disable this function). After testing has been performed parameter is required to be set back
- Install a glad hand on the trailer emergency side and press in the trailer brake valve

Function of Parameter CVU:

- Reduce power during bob tailing



Tags

[k49501063](#)

[13l engine](#)

[volvo](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article

Live UI