
Reference	SSM75617
Models	F-PACE / X761 I-PACE / X590 XE / X760 XF / X260
Title	Near Field Sensing feature degradation (Surround camera; 360 Park Aid) with PIVI B115E-31 DTC only
Category	Electrical
Last modified	30-Nov-2021 00:00:00
Symptom	204000 Instrumentation

Content **Issue**

Near Field Sensing feature degradation with PIVI B115E-31 DTC only.
Surround camera; 360 Park Aid features or any of the feature is not operating. NFSM DTCs are not logged in confirmed/active status, only PIVI B115E-31 in confirmed status.

Cause

Under investigation

Action

Do NOT replace NFSM for this issue!

Before disturbing any components
Please update PIVI using SOTA & Update NFSM module using Pathfinder, to their respective latest available levels.

Note: NFSM is not on SOTA, PathFinder only

If the issue persists, please raise a TA address to EES_320-NFSM team

anBhdHRicnM7MjAyMS0xMj0wMlQxMzoxNzo0Ni41MzZaOzE2NS4yMjUuNTYyMjUwOw==