

Classification:

Reference:

 COPYRIGHT© NISSAN NORTH AMERICA, INC.
 Date:

DA21-008

ITB21-025

November 15, 2021

DTC C1A17-49 STORED IN LASER/RADAR

APPLIED VEHICLES: 2019-2021 QX50 (J55)
 2022 QX55 (FJ55)

SERVICE INFORMATION

If DTC C1A17-49 (ICC SENSOR MALF) is stored in LASER/RADAR in the "PAST" column:

- Erase the DTC.
- DO NOT replace any parts.

If DTC C1A17-49 (ICC SENSOR MALF) is stored in LASER/RADAR in the "CURRENT" column, refer to the applicable ESM for instructions.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 15, 2021	ITB21-025	Original bulletin published

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.