

## Service message "Service A/B Due" in multifunction display cannot be reset

---

Topic number	LI00.20-P-056352
Version	2
Design group	00.20 Maintenance, service system (FSS, ASSYST)
Date	11-15-2016
Validity	MODEL 197.###
Reason for change	Damage code revised
Reason for block	

---

### Complaint:

After a service is performed, the "ASSYST PLUS" cannot be reset.

### Cause:

The distance driven since the last service is less than 1000 km.

### Remedy:

By performing SCN coding of the instrument cluster, the minimum distance between the service intervals is shortened from 1000 km to 100 km.

This allows the "ASSYST PLUS" to be reset after a service is performed when a distance of at least 100 km has been driven since the last service.

<b>Symptoms</b>
Overall vehicle / Maintenance / Active Service System Plus ASSYST PLUS / Implausible

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			54740 90	