

Tech Tip L-TT-0132-13

September 13, 2013

)	(1	V		F	₹e	H	R	e	a	ĪS	t	ra	ıt	id	וכ	n	K	N	it	·h	R	а	d	id	כ	U	J٢	٦i	t	S	v	/a	b
Sed.	and the	and and	-80	ы		-		bed (~					i de	will.			dud.		ė		leaded.	Bud e	-			e de la			Donat		Alberta	1

USA

Audio/Visual/Telematics

Audio/Video

Applicability
2010-2014 Models with Satellite

2010-2014 Models with Satellite Radio

APPLICABLE VEHICLES

2010-2012	HS250H	2013-2014	ES300H
2010-2014	IS250C	2010-2014	ES350
2010	SC430	2010-2014	LS600H
2012	LFA	2010-2014	LS460
2010-2014	GX460	2010-2014	RX450H
2010-2014	IS250	2011-2014	CT200H
2010-2011, 2013- 2014	GS350	2010-2014	IS350
2010-2014	RX350	2010-2014	IS350C
2010-2011	GS460	2010-2011, 2013- 2014	GS450H
2010-2014	IS F	2010-2011, 2013- 2014	LX570

CONDITION

To receive satellite radio functions after the initial trial period has expired, the customer must enter into a contract with XM Satellite Radio Inc. After entering into a contract, registration of an 8-digit XM Radio ID is required. This 8-digit XM Radio ID is found by turning to channel "0" of the satellite radio.

When a new radio head unit is installed in a vehicle, the XM registration does not automatically transfer to the new radio unit.

Note: If the customer does not subscribe to XM services this process is not necessary.

RECOMMENDATIONS

Before removing the old radio, record the original XM Radio ID from channel "0" of the satellite radio.

When the radio is replaced, the new XM Radio ID must be re-registered through XM Satellite Radio Inc. The new XM Radio ID is also found on channel "0" of the new satellite radio.

Re-registration can be done by calling SiriusXM Dealer Support at 1-800-852-9696.

- Provide the old Radio ID and ask to transfer the service on this radio to the new Radio ID.
 Confirm with the agent that the old Radio ID has been deactivated.
- Confirm which services are being transferred (e.g. Audio only or Audio and Traffic and TravelLink.)
- Ask the SXM Dealer Support Agent to send an activation signal to the new radio and confirm
 the radio is working. If necessary, dealer can perform the signal refresh by entering the new
 Radio ID into the SiriusXM Radio Signal Refresh Website (See Linked Reference #1).

In the case that the original Radio ID is not available, the VIN may be used in place of the Radio ID to

Expires on

09/13/2014 Rev1

© 2013, Lexus, a Division of Toyota Motor Sales, USA

Page 1 of 2



Tech Tip L-TT-0132-13

September 13, 2013

XM Re-Registration with Radio Unit Swap

USA

2010-2014 Models with Satellite Radio

determine the account and subscription of the vehicle.

LINK REFERENCES

SiriusXM Radio Signal Refresh Website (www.siriusxm.com/oemrefresh)

Expires on

09/13/2014 Rev1

© 2013, Lexus, a Division of Toyota Motor Sales, USA

Page 2 of 2