

FT5068R2 Hydraulic Tank Rubber Mount Bushing Failures NYCT

Technical writer name
Devanand

Manual section 09

First Level Parts (100% of 251 vehicles)		
Material	Part Number	QTY
Rubber Mount SCB-20I CR-60	N101202	4
Nut Locknyl M8 YZ TRIV 96H 8.8	N44888	4

Nb hours Level 1

1 hr

MQR

7621-1911

Second Level Parts (50% of 251 vehicles)		
Material	Part Number	QTY
Screw M8X40 H YZ TRIV 96H 8.8	N44882-04	4

Disposal of parts

Removed parts are:		When the retained check box is checked, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed.
Discarded	Retained	
x	-	

Client	Order	Road numbers		VIN		QTY	Lang.	Customer	Target market	Plant	Engine Config	Model	NR	R1	R2	R3
New York City Transit - New York	LA73	8504	8507	L82J8J9776445	L82J8J9776476	4	E	NYCT	US	PLB	TD	40	x	x	x	
New York City Transit - New York	LA76	8508	8633	L82J9J9776924	L82J8K9777144	125	E	NYCT	US	PLB	TD	40	x	x	x	
New York City Transit - New York	LB78	8526	8526	L82J3K9776984	L82J3K9776984	1	E	NYCT	US	PLB	TD	40	x	x	x	
New York City Transit - New York	LC32	8634	8754	L82JXK9777145	L82J5K9777277	121	E	NYCT	US	PLB	TD	40	x	x	x	

Jean-Nicolas
Fournier

Digitally signed by Jean-Nicolas Fournier
DN: cn=Jean-Nicolas Fournier, o=Novia Bus,
email=jean-nicolas.fournier@volvo.com, c=CA
Date: 2021.12.15 12:55:57 -05'00'