

**Classification:**

EL17-016C

**Reference:**

ITB17-033C

**Date:**

December 7, 2021

## CLEANING FRONT OR REAR COMBINATION LAMP ASSEMBLIES

This bulletin has been amended. See AMENDMENT HISTORY on the last page.  
Please discard previous versions of this bulletin.

**APPLIED VEHICLES:** 2013-2022 Infiniti

### SERVICE INFORMATION

When cleaning the "Front Combination Lamp" (headlight housing) or "Rear Combination Lamp" (taillight housing) assemblies:

- Use only a mild soap (special vehicle soap or general purpose dishwashing liquid) mixed with clean, lukewarm (never hot) water.
- Use a sponge or soft rag.

### DO NOT USE:

- Strong household soap, strong chemical detergents, gasoline or solvents.

**NOTE:** Some car washes, especially brushless ones, use some acid for cleaning.

- The acid may react with some plastic vehicle components, causing them to crack.
- Always check with your car wash to confirm that acid is not used.

Infiniti's New Vehicle Limited Warranty does not cover physical damage to headlight or taillight housings caused by strong household soap, strong chemical detergents, gasoline or solvents.



Figure 1

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

## AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 27, 2017	ITB17-033	Original bulletin published
March 19, 2018	ITB17-033a	Publication date updated to include the latest models and model years
February 3, 2021	ITB17-033b	<b>APPLIED VEHICLES</b> revised
December 7, 2021	ITB17-033C	<b>APPLIED VEHICLES</b> revised

