

Subject		Market	
Oil Pan #2 Leaks- Under Investigation		USA	
Service Category	Section		
Engine/Hybrid System	Lubrication		
Applicability			
2021-2022 TMMK A25A-FKS/FXS Engines			

APPLICABLE VEHICLES


2021-2022	Avalon HV	2021-2022	Highlander HV
2021-2022	Camry	2021-2022	RAV4 HV
2021-2022	Camry HV	2021-2022	Avalon

CONDITION

Some 2021-2022 TMMK built vehicles with A25A-FKS/FXS engines may exhibit an oil leak from the No.2 Oil Pan. This issue is currently under investigation.

RECOMMENDATIONS

- If you encounter this condition, please do the following:
1. Take clear pictures of the origin of the leak and the identifier information on the outside of the crankcase as shown in below figures.
 2. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair and do not create a TAS case.



Examples of leak origin photos

Subject

Oil Pan #2 Leaks- Under Investigation

Market

USA

Applicability

RECOMMENDATIONS



Crankcase identifier information

LINK REFERENCES

This Tech Tip does not contain any link references