



Volvo Chassis - Certain Volvo Trucks Built After January 11, 2016 May Experience an Issue with the Instrument Cluster Display




> Internal Content

This issue is only a visible issue and has no functional impact to the operation of the vehicle. See pictures below for examples.


Recommended Actions:

There will be new cluster software released to fix this issue in the near future. Currently there is no work to be performed to address this concern.

Rear Axle Temp - GOOD




Rear Axle Temp - BAD



Air Suspension - GOOD

Live UI





Air Suspension - BAD



Favorites Selection - GOOD



Favorites Selection - BAD



Should be "UP" and "DOWN" Arrows

 Tags

[k28535304](#)

[11l engine](#)

[13l engine](#)

[16l engine](#)

[volvo](#)

Related links and attachments

No links or attachments available

 **Feedback**

[Give feedback](#)

to help improve the content of this article