



Volvo Chassis - US10 to US16 Emissions - Soot Level Will Not Reset After Regen Or Locked At 140%



> **Internal Content**

Perform a crystal sublimation while monitoring exhaust temperatures verifying temperatures are reading correctly; after the operation verify the soot level has dropped.



Tags

[k25143190](#)

[volvo](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article