



Bulletin No.: PIT5883

Published date: N/A

Preliminary Information

PIT5883 Information On Vehicles Built With Heated And Vented Seats Disabled / Heated Steering Wheel Disabled / Front Rear Park Assist Disabled

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2022	All	All	All	All
Chevrolet	Silverado	2022	All	All	All	All
Chevrolet	Suburban	2022	All	All	All	All
Chevrolet	Tahoe	2022	All	All	All	All
GMC	Sierra	2022	All	All	All	All
GMC	Yukon Models	2022	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	00G, 00V, 00Y and/or 00Z
Condition	<p>This is an informational PI to bring awareness to certain vehicle options being disabled. Please be aware that some vehicles, identified by an RPO code, are built with the following option(s) disabled:</p> <p>Front and/or Rear Park Assist disabled - RPO's 00Z or 00Y Heated Steering Wheel disabled - RPO 00G Heated/Vented Seats disabled - RPO 00V</p>
Cause	Parts shortage

Correction:

If you have a vehicle with any of these RPO's and a complaint that the option does not work do not perform any repairs at this time. Please reference the following GM GlobalConnect messages for more information:

Front and Rear Park Assist Disabled - Reference Number: GCUS-17-429

Heated Steering Wheel Disabled - Reference Number: GCUS-17-425

Heated/Ventilated Seats Disabled - Reference Number: GCUS-17-424

NOTE: On vehicles with Heated Steering Wheel Disabled, DTC U152B may be set, but it does not turn on any warning messages or lights.

Additional SI Keywords

seat

Version History

Version	1
Modified	01/10/2022 - Created on.



© 2022 General Motors. All Rights Reserved.