



Preliminary Information

PIP5520A Noise From The Park Brake Or Park Brake Is Locked Up

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	LCF	2016 - 2022	All	All	All	All


Involved Region or Country	North America
Condition	There may be a concern with a rattle or scraping noise from the park brake drum, or a concern of the park brake being locked up.
Cause	The vehicle may have been driven with the park brake engaged.

Correction:

Please review the following pictures, they all indicate the vehicle being driven with the park brake being engaged.







If this is encountered check the operation of the park brake indicator by lifting up on the park brake lever.

The lamp should be on before the first click. If park brake lamp is not working diagnosis and repair as need.

For the damaged park brake review the bulletin below due to the labor operation is restricted.

Please review the latest version of bulletin [16-NA-274: Fleet Action Center \(FAC\) Labor Operation Restrictions and Repair Restrictions for US Medium Duty Dealers](#).

Version History

Version	1
Modified	PIP5520 Created on 09/13/2017 PIP5520A - updated model years on 01/28/2022



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.