



# Preliminary Information

## PIT5762E History DTCs To Ignore / NO SES / NO Malfunction Indicator Lamps / NO Warning Messages

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2020 - 2022	All	All	All	All
Cadillac	CT5	2020 - 2022	All	All	All	All
Cadillac	Escalade Models	2021 - 2022	All	All	All	All
Chevrolet	Corvette	2020 - 2022	All	All	All	All
Chevrolet	Suburban	2021 - 2022	All	All	All	All
Chevrolet	Tahoe	2021 - 2022	All	All	All	All
GMC	Yukon Models	2021 - 2022	All	All	All	All

Involved Region or Country	North America
Condition	A technician may find any number of the following DTCs set in History. These history DTC's will NOT cause any SES, MIL's or Warning messages. The DTCs may include any number of DTCs listed in the table below.
Cause	Software Anomaly

**Correction:**

If any of the DTCs listed in the table below are set in History they should be ignored. There will be NO customer concerns or indication to the customer that these DTC's are set in history. If these DTCs are Current, do NOT ignore them, but diagnose as normal.

The following DTC's should be ignored if set as history:

Module	DTC#	Description
K164 - Differential Control Module	U3000-49	Control Module Internal Electronic Failure
K69 - Transfer Case Control Module	U1611-00	Lost Communication with Engine Control Module on CAN Bus 2
K69 - Transfer Case Control Module	U0101-00	Lost Communication with Transmission Control Module
K69 - Transfer Case Control Module	U0131-00	Lost Communication with Electronic Power Steering Module - Processor 1
K69 - Transfer Case Control Module	U0151-00	Lost Communication with Inflatable Restraint Sensing and Diagnostic Module
K69 - Transfer Case Control Module	U1610-00	Lost Communication with Brake System Control Module 1 on CAN Bus 2

K160 - Brake System Control Module	U0131-00	Lost Communication with Electronic Power Steering Module - Processor 1
K160 - Brake System Control Module	U043A-00	Invalid Data Received from Electronic Suspension Control Module
K160 - Brake System Control Module	U0452-00	Invalid Data Received from Inflatable Restraint Sensing and Diagnostic Module
K160 - Brake System Control Module	U0155-00	Lost Communication with Instrument Panel Cluster
K160 - Brake System Control Module	U1615-00	Lost Communication with External Object Calculating Module/EOCM_HCP1 on CAN Bus 2
K160 - Brake System Control Module	U0151-00	Lost Communication with Inflatable Restraint Sensing and Diagnostic Module
K160 - Brake System Control Module	U1607-00	Lost Communication with Central Gateway Module on CAN Bus 1
K160 - Brake System Control Module	U0423-00	Invalid Data Received from Instrument Panel Cluster
K160 - Brake System Control Module	U0140-00	Lost Communication with Body Control Module
K160 - Brake System Control Module	U0403-00	Invalid Data Received from Transfer Case Control Module
K160 - Brake System Control Module	U1608-00	Lost Communication with Serial Data Gateway Module on CAN Bus 2
K160 - Brake System Control Module	U1611-00	Lost Communication with Engine Control Module on CAN Bus 2
K124 - Image Processing Module	U0131-00	Lost Communication with Power Steering Control Module
K124 - Image Processing Module	U0512-00	Invalid Data Received from Seat Memory Control Module - Driver
K124 - Image Processing Module	U0151-00	Lost Communication with Inflatable Restraint Sensing and Diagnostic Module
K43 - Power Steering Control Module	U3003-1C	Battery Voltage Circuit Voltage Out of Range
K43 - Power Steering Control Module	U3003-16	Battery Voltage Below Threshold
B174W - Front Camera Module	U0447-00	Invalid Data Received from Central Gateway Module
B174W - Front Camera Module	U0447-01	Invalid Data Received from Central Gateway Module
B174W - Front Camera Module	U0422-00	Invalid Data Received From Body Control Module
B174W - Front Camera Module	U0452-00	Invalid Data Received from Inflatable Restraint Sensing and Diagnostic Module
B174W - Front Camera Module	U0140-00	Lost Communication with Body Control Module
B174W - Front Camera Module	U0155-00	Lost Communication with Instrument Panel Cluster
B174W - Front Camera Module	U0401-00	Invalid Data Received from Engine Control Module
B174W - Front Camera Module	U0418-00	Invalid Data Received from Brake System Control Module 1
B174W - Front Camera Module	U0420-00	Invalid Data Received from Power Steering Module
B174W - Front Camera Module	U0421-00	Invalid Data Received from Automatic Level Control Module
B174W - Front Camera Module	U0423-00	Invalid Data Received from Instrument Panel Cluster Control Module
B174W - Front Camera Module	U1611-00	Lost Communication with Engine Control Module on CAN Bus 2
K219 - Lighting Control Module	U0422-00	Invalid Data Received from Body Control Module
K26 - Headlamp Control Module (Escalade	U0422-	Invalid Data Received from Body Control Module

Only)	00	
A26 - Heater and Air Conditioning User Interface Control - Front	U0422-00	Invalid Data Received from Body Control Module
P16 - Instrument Panel Cluster	U1008-00	Loss of Ethernet Link
P16 - Instrument Panel Cluster	U197F-00	Odometer Value Mismatch
P16 - Instrument Panel Cluster	U0485-00	Invalid Data Received from Radio
K180 Driver Monitoring System Module	U0131-00	Lost Communication with Power Steering Module
T3 - Audio Amplifier	U1008-29	Loss of Ethernet Link - General Signal Failure
A11 - Radio	U0140-00	Lost Communication with Body Control Module
A11 - Radio	U0146-00	Lost Communication with Central Gateway Module
A11 - Radio	U0155-00	Lost Communication with Instrument Panel Cluster
B233B - Long Range Radar	U053B-00	Invalid Data Received from External Object Calculating Module/EOCM_HCP1
B233B - Long Range Radar	U0447-00	Invalid Data Received from Serial Data Gateway Module
K40D - Drivers Memory Seat Module	U0209-00	Lost Communication with Seat Bolster Memory Control Module - Driver
K40D - Drivers Memory Seat Module	B196D-49	Front Seat Bolster Memory Control Module - Driver - System Internal Failure
K40D - Drivers Memory Seat Module	U1962-00	Unable to Authenticate Serial Data Message
K40P Passenger Seat Adjuster Memory Module	U0210-00	Lost Communication with Front Seat Bladder Control Module - Passenger
K73 - Telematic/OnStar Module	U1611-00	Lost Communication with Engine Control Module on CAN Bus 2
K73 - Telematic/OnStar Module	U0140-00	Lost Communication with Body Control Module
K73 - Telematic/OnStar Module	U0155-00	Lost Communication with Instrument Panel Cluster
K73 - Telematic/OnStar Module	U1008-00	Loss of Ethernet Link
K73 - Telematic/OnStar Module	U0146-00	Lost Communication with Central Gateway Module
K73 - Telematic/OnStar Module	U0151-00	Lost Communication with Restraints Control Module
K73 - Telematic/OnStar Module	U160F-00	Lost Communication with Brake System Control Module 1 on CAN Bus 1
K9 - Body Control Module	U065F-00	Lost Communication with Rear Temperature Valve Actuator - Left
K9 - Body Control Module	U0663-00	Lost Communication with Rear Mode Valve Actuator - Left
K9 - Body Control Module	U152B	Body Control Module LIN Bus 7
K182 - Parking Assist Control Module	U0131-00	Lost Communication with Power Steering Module
K182 - Parking Assist Control Module	U0140-00	Lost Communication with Body Control Module
K182 - Parking Assist Control Module	U1611-00	Lost Communication with Engine Control Module on CAN Bus 2
K182 - Parking Assist Control Module	U1614-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 1
K182 - Parking Assist Control Module	U1615-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 2
K182 - Parking Assist Control Module	U1610-	Lost Communication with Brake System Control Module 1

	00	on CAN Bus 2
K182 - Parking Assist Control Module	U160F-00	Lost Communication with Brake System Control Module 1 on CAN Bus 1
K182 - Parking Assist Control Module	U1608-00	Lost Communication with Serial Data Gateway Module on CAN Bus 2
K182 - Parking Assist Control Module	U1607-00	Lost Communication with Serial Data Gateway Module on CAN Bus 1
K182 - Parking Assist Control Module	U0422-00	Invalid Data Received from Body Control Module
K182 - Parking Assist Control Module	U0420-00	Invalid Data Received from Power Steering Module
K182 - Parking Assist Control Module	U0418-00	Invalid Data Received from Brake System Control Module 1
K182 - Parking Assist Control Module	U0402-00	Invalid Data Received from Transmission Control Module
K182 - Parking Assist Control Module	U0101-00	Lost Communication with Transmission Control Module
K182 - Parking Assist Control Module	U0146-00	Lost Communication with Central Gateway Module
K182 - Parking Assist Control Module	U160F-00	Lost Communication with Brake System Control Module 1 on CAN Bus 1
K60 - Column Lock Module	U0101-00	Lost Communication with Transmission Control Module
K60 - Column Lock Module	U3000-41	Control Module General Checksum Failure
M101R - Front Seat Belt Retractor Motor - Right	U0447-00	Invalid Data Received from Serial Data Gateway Module
M101R - Front Seat Belt Retractor Motor - Right	U0422-00	Invalid Data Received from Body Control Module
M101L - Front Seat Belt Retractor Motor - Left	U0447-00	Invalid Data Received from Serial Data Gateway Module
M101L - Front Seat Belt Retractor Motor - Left	U0422-00	Invalid Data Received from Body Control Module
B233LF - Short Range Radar Sensor - Left Front	U1616-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 8
B233RF - Short Range Radar Sensor - Right Front	U1616-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 8
B233LR - Short Range Radar - Left Rear	U1616-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 8
B233RR - Short Range Radar Sensor - Right Rear	U1616-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 8
B233SR Short Range Radar Rear Side Sensor - Right	U1616-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 8
B233SL Short Range Radar Rear Side Sensor - Left	U1616-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 8
K157 - Video Processing Module	B1598-29	Sideview Camera - Left Signal Invalid
K157 - Video Processing Module	B1A68-92	Frontview Camera Performance or Incorrect Operation
K157 - Video Processing Module	U0131-00	Lost Communication with Electronic Power Steering Module - Processor 1
K157 - Video Processing Module	U1614-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 1
K157 - Video Processing Module	U053B-00	Invalid Data Received from Image Processing Module 1 - Processor 1
K157 - Video Processing Module	U0422-00	Invalid Data Received from Body Control Module
K157 - Video Processing Module	U0140-00	Lost Communication with Body Control Module
K157 - Video Processing Module	U0146-00	Lost Communication with Central Gateway Module

K157 - Video Processing Module	U0420-00	Invalid Data Received from Power Steering Module
K157 - Video Processing Module	U0447-00	Invalid Data Received from Serial Data Gateway Module
K157 - Video Processing Module	U1615-00	Lost Communication with Image Processing Module 1 - Processor 1 on CAN Bus 2
K157 - Video Processing Module	U0155-00	Lost Communication with Instrument Panel Cluster
K157 - Video Processing Module	U0151-00	Lost Communication with Restraints Control Module

### Additional SI Keywords

U043A, U053B, U0101, U0131, U0140, U0146, U0151, U0155, U0209, U0422, U0423, U0447, U0452, U0512, U1008, U1607, U1611, U1615, U1962, U197F, U3000, U3003

### Version History

Version	5
Modified	<p>07/30/2020 - Created.</p> <p>08/11/2020- Updated to remove Labor operation statement per request from BQM Brian Combs</p> <p>09/29/2020- Added DTC U0422 to the ignore list</p> <p>02/18/2021 - Updated Title, Condition, Cause and Correction sections.</p> <p>10/07/2021 - Update to the model list.</p> <p>1/31/2022 - Update to the cause section</p>



© 2022 General Motors. All Rights Reserved.