

SSM 50503 - 2020-2022 F-Super Duty - 6.7L - Cooling Fan Noisy And/Or Runs Continuously

Some 2020-2022 F-Super Duty vehicles equipped with a 6.7L engine may exhibit a cooling fan with excessive noise or stays on continuously. The Workshop Manual (WSM), Section 303-03 Engine Cooling > Diagnosis and Testing > Cooling Fan Control, pinpoint test (PPT) AH has been updated to improve diagnostics and reduce unnecessary cooling fan clutch replacements.

APPLICABLE VEHICLES
2020 - 2022 TRUCK: FE P558N SUPER DUTY

ERROR: syntaxerror
OFFENDING COMMAND: --nostringval--

STACK:

```
(
  ~ ~ ~ ~
  6 N f ~ fi fi ~ b " '
)
(
  ~ i # i # i # i # i # i # i # i # i # i # i # i # Z < D a D a D a D a D
)
(
  cvt „p 5 < ...fpgm~ 7 h +glyph>]1 P ` head!My- 6hhea > k
)
-mark-
/sfnts
```