

Technical product information

Topic	V8 Kovomo - Bentayga - Water pump drive gear cover (Deletion)
Market area	Russische Föderation (5RU),Australia E04 Bentley rest Asia and Australia (6E04),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2065918/1
Level	EH
Status	Approval
Release date	

New customer code

Object of complaint	Complaint type	Position
engine -> engine operation -> engine refinement	noise, vibration -> noise	
engine -> gear drive, chain drive, belt drives -> coolant pump pulley	noise, vibration -> noise	

Vehicle data

V8 Kovomo engine

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V14D9	2018	E		*	*	*
4V14D9	2019	E		*	*	*

Documents

Document name
master.xml

Customer statement / workshop findings

Workshop findings:

The original water pump has a cover fitted directly over the top of the water pump drive gear (Figure 1)



Figure 1

However the replacement water pump does not have a cover fitted (Figure 2)



Figure 2

Technical background

▪

The cover is no longer fitted on replacement water pumps, the cover is not required and MUST not be transferred to the new water pump

The operative should fit the new water pump without the cover as shown in Figure 2

NOTE: DISS queries or Service calls should not be submitted for this concern

Production change

Not applicable

Measure

Not applicable