

## **Diagnostic Trouble Code (DTC) P04DB - Crankcase Ventilation Disconnected; US10+OBD13 To US14+OBD16 Emissions**



> Internal Content

If Tech Tool concludes no fault found for DTC P04DB Crankcase Ventilation: Disconnected Pipe/Separator Monitor, verify that there are absolutely no leaks around the crankcase vent elbow, valve cover connection, or tube connection at the CCV housing. The integrity of the flex portion of the oil fill tube and the seal for the oil level dipstick should be verified.



k23884537 p04db-00 p04db00

crankcase ventilation mack volvo

## Related links and attachments

No links or attachments available



Give feedback

to help improve the content of this article