



Technical Service Bulletin

PSS 90 Head-up display: Navigation directions are not displayed

90 22 49 2065815/2 March 7, 2022. Supersedes Technical Service Bulletin Group 90 number 22-40 dated January 31, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022	All	Head Up Display

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised service (updated expected release date) Revised header (Corrected part number filter)
1	01/31/2022	Initial publication

Customer states:

No navigation map or directions are displayed on the heads-up display (HUD).

All other information is displayed properly.





Technical Service Bulletin

Figure 1: navigation information missing in HUD

Technical Background

A software malfunction may cause the navigation data not to be displayed on the HUD.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

1. Explain to the customer that a solution is forthcoming by the end of the 4th quarter of 2022 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance page in Elsa.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2065815) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.