

Technical Service Bulletin

91 Park assist plus: currently unavailable message displayed in the MMI while located in NY or VT 91 22 83 2066110/1 March 4, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e- tron GT	2022 – 2023	All	Not Applicable

Condition

Customer states:

• The park assist plus system does not activate when pushing the park assist plus button.

The message "Park assist plus: currently

unavailable" is displayed on the MMI screen.



Figure 1: Park assist plus button



Figure 1: Park assist plus: currently unavailable message

Workshop findings:

• No relevant DTCs are stored.

Technical Background

Park assist plus is currently geofenced to be unavailable if the vehicle is physically located in one of the following states:

- New York
- Vermont

Page 1 of 2

^{© 2022} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prin expressed written permission of the publisher.



Technical Service Bulletin

Production Solution

Not applicable.

Service

No repair is available at this time as the vehicle is operating as designed.

- 1. Do not perform any repairs. Any repairs for this concern may be denied.
- 2. Instruct the customer that this condition is normal.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2066110) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prin expressed written permission of the publisher.