



Thor Motor Coach Technical Service Bulletin

TSB #	TSB 22-04		
Description/Title:	Ford Transit USB dash delete		
Affected Product Line(s):	Certain model year 2022 Gemini/Compass		
Service Campaign # :	RC000259	Released Date:	3/28/2022
Codes:	Inspect Only: TMCTS80273Y Inspect with Repair: TMCTS80273W	Document Date:	3/28/2022
Time Allowed:	Inspect Only: 0.1 Inspect with Repair: 0.2	Document Revision:	A

Issue:

Original Ford USB in dash is non-functioning. TMC uses an upgraded radio in place of the Ford OEM radio, and this USB is no longer supported.

Tools Required:

- Flat head screw driver

Part(s) Required:

0479524 - FASTENER, PANEL, BLACK, .375 HOLE, 1" HEAD, CHRISTMAS TREE PLUG

Shop part may be used in place of ordering part from TMC if available

Instructions:

Use a flat head screw driver to push the USB outlet straight in towards the dash until the USB disconnects from the dash. Insert panel fastener in place where USB was in the dash.

