



Mack Chassis - Diagnostic Trouble Code (DTC) P249C Intermittently Lighting The Malfunction Indicator Lamp (MIL) - US14+OBD15 And US14+OBD16 (Non-Common Rail Fuel System) Emissions, Common Model Years 2016 and 2017



> Internal Content

Software improvements have been released for both emissions levels to address this DTC.



Tags

[k18304613](#)

[p249c-00](#)

[p249c00](#)

[mack](#)

Related links and attachments

[KC-251 FSB 284-065](#)

[KC-251 FSB 284-064](#)



Feedback

[Give feedback](#)

to help improve the content of this article