



Mack Chassis - Diagnostic Trouble Code (DTC) P0471 Illuminating The Malfunction Indicator Lamp (MIL) - US17+OBD16, US17+OBD18 (GHG17, Common Rail Fuel System) Chassis With Turbo Compound ONLY



> Internal Content

Software improvements have been made that address this DTC.



Tags

[k04247174](#)

[p0471-64](#)

[p047164](#)

[mack](#)

Related links and attachments

[KC-330 FSB 284-067](#)

[KC-330 REF KC-908](#)



Feedback

[Give feedback](#)

to help improve the content of this article