



Thor Motor Coach Technical Service Bulletin

TSB #	TSB 22-05		
Description/Title:	Gemini/Compass rearview monitor splitter.		
Affected Product Line(s):	2022		
Service Campaign # :	RC000261	Released Date:	
Codes:	Inspect Only: Inspect with Repair:	Document Date:	4/12/2022
Time Allowed:	Inspect Only: 0.1 TMCTS80248Y Inspect with Repair: 0.3 TMCTS80248W	Document Revision:	A

Issue:

This splitter sends the backup camera signal to both inputs of the monitor. Without it you can only view the camera in reverse, not while driving down the road.

Tools Required:

- Black electrical tape

Part(s) Required:

344946 – Splitter

Instructions:

1. Turn on the ignition and then hit the button on the monitor. It should turn on and display the camera image if the splitter is installed (No further action is required). If the splitter is not installed it will just stay blank. (Proceed to repair instructions below).



Thor Motor Coach Technical Service Bulletin

2. Area shown below is where connection is made.



3. Pull the plastic cover away from the top of the driver's side wheel well. The connection should be in a bundle right above the wheel well.



4. Pull the bundle down for better access. Remove electrical tape from bundle and install splitter



5. The picture below is how the connections look when the splitter is installed correctly. Once installation is complete re-tape the wires into a bundle and put bundle back up behind the plastic and reinstall plastic cover.



6. Test for correct function by turning on the ignition and then hitting the button on the monitor. It should turn on and display the camera image if installed correctly. Also test by putting the coach into reverse and ensuring camera is operational.