

Seat Heating Nonfunctional, LEDs active

Topic number	LI91.30-P-074540
Version	1
Function group	91.30 - Seat heater, seat ventilation
Date	3/23/22
Validity	All vehicles in model series X290 with code 873 (Seat heating) and with code 275 (Memory function).
Reason for change	

Complaint

The seat heating for the front seats is nonfunctional, the LEDs on the buttons are however, active.

Cause

Faulty coding.

Remedy

1. Coding of control unit N10/8 - Rear signal acquisition and actuation module (SAM-H).
2. Commissioning of front seat heating.

If problem persists, please open a PTSS case with a short video showing complaint.

Symptoms				
Body > Seat > Seat heater/comfort heater > Seat heater nonfunctional				
Control unit/fault code				
Control unit		Fault text		
N10/8 - Rear signal acquisition and actuation module (Rear SAM)				
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note