

**FT5253 Retorque Hose Clamp**

**Technical writer name**  
Rajendra N M

**Manual section** 09

**Nb hours Level 1** 0.33 hr

**MQR** 7621-2450


Part Description	Part Number	QTY
-	-	-

Disposal of parts		
Removed parts are:		When the retained check box is checked, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed.
Discarded	Retained	
-	-	

Client	Order	Road numbers		VIN		QTY	Lang.	Customer	Target market	Plant	Engine Config	Model	NR	R1
Trimet Portland Oregon	LD15	4502	4502	S92J6M9778188	S92J6M9778188	1	E	-	US	PLB	TD	60	x	
Trimet Portland Oregon	LD15	4504	4504	S92J4M9778190	S92J4M9778190	1	E	-	US	PLB	TD	60	x	
Trimet Portland Oregon	LD15	4508	4508	S92J1M9778194	S92J1M9778194	1	E	-	US	PLB	TD	60	x	
Trimet Portland Oregon	LD15	4510	4510	S92J2M9778205	S92J2M9778205	1	E	-	US	PLB	TD	60	x	
Trimet Portland Oregon	LD15	4512	4512	S92J9M9778217	S92J9M9778217	1	E	-	US	PLB	TD	60	x	

Jean-Nicolas Fournier

Digitally signed by Jean-Nicolas Fournier  
 DN: cn=Jean-Nicolas Fournier, o=Nova Bus,  
 email=jean-nicolas.fournier@volvo.com, c=CA  
 Date: 2022.04.04 09:42:46 -04'00'



5 hoses and 10 clamps  
need the torque Validated