

# Volvo Proprietary Steerable Axle Hubcap Replacement

Service Category Service Department

Section 771

Technician Skill Level C

Market US, Canada

### Applicability

**VOLVO**

Years	Models
2021 - 2023	VAH, VHD, VN, VNE

### Introduction

This Service Campaign is the solution for the **Proprietary Hubcap Recall SC0425** that effected **Volvo VAH, VHD, VN, VNE** Models. This Service Campaign also covers trucks that were shipped short from the factory or removed in the field. Volvo Trucks now has a solution to replace the Proprietary Hubcaps with new updated hubcaps.

### Production Change Information

This bulletin applies to vehicles built within the specified production changes below.

Brand	Engine	Emission Level	Starting Build Date	Ending Build Date
Volvo	CU15, D11, D13, UE	USA17-24, ZE	08- September-2020	14-January-2022

### Warranty Information

<b>This repair is covered by an authorized Service Program. Reimbursement is obtained through the normal claim handling process.</b>			<b>B</b>
Main Labor Code	Description	Hours	
7718-03-02-01	Hub Cap Wheel Cover, Replacement Per wheel	0.1	
Causal Part	<b>23768767 / 23768768</b>		
SCC Authorization Code	<b>S7631</b>		
Expiration Date	<b>April 30, 2023</b>		

## Volvo Proprietary Steerable Axle Hubcap Replacement

---

### Parts Information

- Verify parts and quantity needed in IMPACT per VIN .  
Each kit below contains 2 hub caps.

Part Numbers	Part Names	Quantity
24154261	HUB CAP, KIT, STEER, VOLVO, BLACK	*
24154263	HUB CAP, KIT, STEER, VOLVO, CHROME	*

### Required Tools & Equipment

- N/A

### Calibration Information

- N/A

### Repair Procedure

1. Secure truck for service.
2. Install all new proprietary hubcap wheel covers.
3. Ensure new hubcaps are fully seated on the wheel.
4. Release the truck to service.

Volvo Proprietary Hubcap wheel cover shown below

