

GUARDDOG CONNECT



DTC: SPN 5903 FMI 21

Bulletin: GDC22-370

Date: April 01, 2022

Description: See below for fault code description(s)

Applies to: US ARMY VEHICLES

General Information

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
SPN 5903 FMI 21	Pressure Control Solenoid (PCS) 4 Stuck Off – Data Drifted Low	N/A	N/A

Required Parts

Part Number	Description	Quantity
N/A	PTT, VOCOMII	1

Repair Instructions

Please reference the following file(s):

- IETM, WP File Name: **T00702**
- IETM, WP Number: **437**

Additional Resources

- For support with a warrantable fault/fault code, please submit an SF368 Product Quality Deficiency Report (PQDR) in the Product Data Reporting & Evaluation Program (PDERP) at <https://www.pdrep.csd.disa.mil/> and CC or forward the PDREP generated .pdf copy of the SF368 to appropriate Mack Defense Warranty Managers:

Margaret Baranowski
(484)-743-7127
margaret.baranowski@mackdefense.com

William Beard
(610)-573-4954
william.beard@mackdefense.com

DTC: SPN 5903 FMI 21

Bulletin: GDC22-370

Date: April 01, 2022

- For assistance with normal service or technical related questions, please contact our Contractor Logistics Support (CLS) provider POCs:

Rich Rader
(910) 797-0903
richard.rader@mantech.com

Gil Esplana
(254) 404-5409
gil.esplana@mantech.com