GUARDDOG CONNECT



DTC: P0108-00 **Bulletin**: GDC22-172

Date: April 01, 2022

Description: See below for fault code description(s)

Applies to: US ARMY VEHICLES

General Information

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
P0108-00	IDTC_BOOSTPRES_ SCH – Voltage Above Normal or Shorted High	 Connector Wiring harness Intake manifold air temperature (IMAT) and pressure sensor Engine control module (ECM) 	 Low Power The charge pressure gauge shows 0 in the instrument, if the signal wire is short-circuited to 5 V or to battery voltage The charge pressure gauge always displays pressure if there is open circuit on the ground wire

Required Parts

Part Number	Description	Quantity
N/A	PTT, VOCOMII	1

Repair Instructions

Please reference the following file(s):

IETM, WP File Name: T00803IETM, WP Number: 172

Additional Resources

 For support with a warrantable fault/fault code, please submit an SF368 Product Quality Deficiency Report (PQDR) in the Product Data Reporting & Evaluation Program (PDERP) at https://www.pdrep.csd.disa.mil/ and CC or forward the PDREP generated .pdf copy of the SF368 to appropriate Mack Defense Warranty Managers:

Margaret Baranowski (484)-743-7127 margaret.baranowski@mackdefense.com

William Beard (610)-573-4954 william.beard@mackdefense.com

GUARDDOG CONNECT



DTC: P0108-00 **Bulletin**: GDC22-172

Date: April 01, 2022

• For assistance with normal service or technical related questions, please contact our Contractor Logistics Support (CLS) provider POCs:

Rich Rader (910) 797-0903 richard.rader@mantech.com

Gil Esplana (254) 404-5409 gil.esplana@mantech.com