GUARDDOG CONNECT



DTC: P111E-00 **Bulletin:** GDC22-180

Date: April 01, 2022

Description: See below for fault code description(s)

Applies to: US ARMY VEHICLES

General Information

These repair instructions are intended to address the following fault(s):

DTC	Description	Possible Cause	Possible (Observable) Symptoms
P111E-00	IDTC_COOLTEMP_ MHI – High- Moderate Severe (2)	 Engine cooling fan Fan belt Thermostat Low coolant level Clogged radiator Clogged cooling system Coolant pump drive belt Coolant pump belt tensioner Slipping impeller Poor flow-through in the cooling system Pressure cap, expansion tank Engine coolant temperature sensor Coolant pump Engine control module (ECM) 	Engine de-rated

Required Parts

Part Number	Description	Quantity
N/A	PTT, VOCOMII	1

Repair Instructions

Please reference the following file(s):

IETM, WP File Name: T00027IETM, WP Number: 243

GUARDDOG CONNECT



DTC: P111E-00 **Bulletin**: GDC22-180

Date: April 01, 2022

Additional Resources

For support with a warrantable fault/fault code, please submit an SF368 Product Quality Deficiency Report
(PQDR) in the Product Data Reporting & Evaluation Program (PDERP) at https://www.pdrep.csd.disa.mil/
and CC or forward the PDREP generated .pdf copy of the SF368 to appropriate Mack Defense Warranty
Managers:

Margaret Baranowski (484)-743-7127 margaret.baranowski@mackdefense.com

William Beard (610)-573-4954 william.beard@mackdefense.com

 For assistance with normal service or technical related questions, please contact our Contractor Logistics Support (CLS) provider POCs:

Rich Rader (910) 797-0903 richard.rader@mantech.com

Gil Esplana (254) 404-5409 gil.esplana@mantech.com