

# Technical Journal

TITLE:

**Seat belt catch, foreign objects**

<b>REF NO:</b> TJ 19383.8.0	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2022-03-21	<b>STATUS DATE:</b> 2022-03-24
<b>FUNC GROUP:</b> 8843	<b>FUNC DESC:</b> Catch for safety belt	Page 1 of 2	

## “Right first time in Time”

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

### DESCRIPTION:

When analyzing replaced seat belt catches, we have found catches with coins, candy, nuts etc inside, causing the problem.

\* Vehicle type 539 has been added.

\* VST Operation No. deleted

### CSC Customer Symptom Codes

Code	Description
VU	Seat belt and other safety systems/Buckle latching problems

### DTC Diagnostic Trouble Codes

### Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124							2007-2016		-	0-0
134							2011-9999		-	0-0
135							2008-2016		-	0-0
136							2008-2016		-	0-0
137							2016-9999		-	0-0

# Technical Journal 19383.8.0

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
138							2014-9999		-	0-0
144							2009-2015		-	0-0
155							2011-9999		-	0-0
156							2009-9999		-	0-0
157							2015-9999		-	0-0
184							1999-2006		-	0-0
224							2019-9999		-	0-0
225							2019-9999		-	0-0
227							2019-9999		-	0-0
234							2017-9999		-	0-0
235							2017-9999		-	0-0
236							2017-9999		-	0-0
238							2018-9999		-	0-0
246							2018-9999		-	0-0
256							2016-9999		-	0-0
275							2003-2016		-	0-0
285							2000-2008		-	0-0
295							2001-2007		-	0-0
384							2001-2009		-	0-0
525							2013-9999		-	0-0
526							2013-9999		-	0-0
533							2007-2013		-	0-0
536							2018-9999		-	0-0
539							2022-9999		-	0-0
542							2006-2013		-	0-0
544							2004-2012		-	0-0
545							2004-2012		-	0-0

**Service:**

Before replacement, the belt catch must be checked if there is any kind of foreign objects inside. If there are objects inside the belt catch try to carefully remove the object with vacuum cleaner or compressed air. **Do not use** a screwdriver or similar. Then check that the function of the belt catch is ok.

*No Warranty claims will be accepted for this TJ.*

**VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 8843.