

Reference SSM62657

XK / X150

Models XJ / X351

XF / X250

Title Hood / Bonnet Ajar Switch

Category Body

Last modified 08-Feb-2013 00:00:00

Symptom 112000 Latches/Locks & Security

Issue:

Open Bonnet warning on message centre.

Cause:

Ajar switch is not secure to latch assy or faulty switch.

Content

Action:

Jaguar request dealers not to repair / refit and adjust the switch to address this reported fault. Where this occurs replace the switch to effect a repair.