

TECHNICAL BULLETIN 222: 8 UPDATES



Notice Information

Ref	20680
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (US&CA) - February 1, 2022

TOL Ref. # 20680-SVC

TECHNICAL BULLETIN 222: 8 UPDATES

Triumph has released [Technical Bulletin 222](#) including 8 subjects across a range of models. This, and all technical bulletins can be found on TriumphOnline.net (TOL) [Technical Bulletin Page](#). Please print and ensure that all relevant staff in your dealership/market are familiar with the action.

PLEASE ENSURE ABSENT STAFF ARE INFORMED ON THEIR RETURN.

Contents		
Item	Subject	Model Affected
222.1	Home Button Operation for Models with TFT Instruments	Tiger 800 XR, Tiger 900, Tiger 800 XRX, Tiger 900 GT, Tiger 800 XCX, Tiger 900 Rally, Tiger 800 XRT, Tiger 900 GT Pro, Tiger 800 XCA, Tiger 900 Rally Pro, Tiger 800 XRX - LRH, Tiger 900 GT - LRH, Tiger 850 Sport, Scrambler 1200 Bond Edition, Scrambler 1200 Steve McQueen Edition, Scrambler 1200 XC, Scrambler 1200 XE, Daytona Moto2™ 765, Daytona Moto2™ 765, Street Triple R, Street Triple R - LRH, Street Triple RS, Speed Triple S, Speed Triple RS, Speed Triple 1200 RS, Speed Triple 1200 RR, Tiger 1200 XRX, Tiger 1200 XCX, Tiger 1200 XRT, Tiger 1200 XCA, Tiger 1200 XRX - LRH, Tiger 1200 Alpine, Tiger 1200 Desert, Rocket 3 GT Triple Black, Rocket 3 R Black, Rocket 3 GT, Rocket 3 R, Rocket 3 TFC
222.2	Fuel Tank Drain Hose Routing	Daytona Moto2™ 765
222.3	Misdetection of Diagnostic Trouble Codes (DTCs)	Street Scrambler Sandstorm, Street Twin Goldline, Scrambler 1200 Steve McQueen Edition, Bonneville T100, Street Scrambler, Speed Twin, Thruxton RS,

		Street Twin, Scrambler 1200 XC, Scrambler 1200 XE, Bonneville T120 Black, Bonneville T120, Bonneville Bobber, Speed Triple 1200 RS
222.4	Rebound Adjuster Parts Kit	Scrambler 1200 Bond Edition, Scrambler 1200 Steve McQueen Edition, Scrambler 1200 XC, Scrambler 1200XE
222.5	Introduction of New Instrument Hardware	Trident 660
222.6	Handbook Changes	All models from 2022
222.7	Triumph Diagnostic Tool - New Diagnostic functionality	Speed Triple 1200 RR
222.8	Triumph Technical Information - Site Overview	All Models

Consult **Triumph Online (TOL) / Technical Bulletin Page** (Bulletin #222) or the attached **Technical Bulletin 222** PDF for additional information.

Reminder: Use the **“VIN Enquiry”** function within TOL (found under the **Service / Technical** drop-down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives, or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.