



Technical Service Bulletin

90 Instrument Cluster: CNG mode active or CNG inspection message is erroneously displayed

90 22 65 2067182/1 May 27, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4 allroad, A4, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, RS 5 Sportback, A6, A6 allroad, S6, RS 6 Avant, A7, A7 e quattro, S7, RS 7, A8, S8, e-tron quattro, e-tron Sportback quattro, e-tron GT, RS e-tron GT, Q5, Q5 e quattro, SQ5, SQ5 Sportback, Q7, SQ7, Q8, SQ8, RS Q8, Q5 Sportback, A4 allroad, A4, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, RS 5 Sportback, A6, A6 allroad, S6, RS 6 Avant, A7, A7 e quattro, S7, RS 7, A8, S8, e-tron quattro, e-tron Sportback quattro, e-tron GT, RS e-tron GT, Q5, Q5 e quattro, SQ5, SQ5 Sportback, Q7, SQ7, Q8, SQ8, RS Q8, and Q5 Sportback	2022	All	Audi Virtual Cockpit Gen2+

Condition

Customer states:

A message regarding CNG inspection or CNG mode is displayed on the instrument cluster, despite the vehicle not being equipped with a CNG fuel system (Figure 1).



CNG inspection due! CNG mode not available. Please contact workshop



Technical Service Bulletin


 CNG mode not available in XXX.
Please contact workshop

Figure 1. Examples of the possible error message.

The message is displayed very sporadically and is no longer displayed after an ignition cycle.

Therefore, it may not be reproducible.

Technical Background

A highly sporadic startup timing issue can cause this message to be displayed erroneously.

Production Solution

Not applicable.

Service


No repair is available at this time.

1. Do not perform any repairs. Repairs for this concern may be denied by warranty.
2. Instruct the customer that this condition is normal and that the complaint can be resolved by cycling the ignition.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information



Technical Service Bulletin

All part and service references provided in this TSB (**2067182**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.