

NTG7 navigation map data: Wrong curve direction shown in the instrument cluster

Topic number	LI82.85-P-074800
Version	1
Function group	82.85 - Navigation and Communication systems
Date	5/16/22
Validity	Model series 206, 223, and 297 with code K34 and NTG7 map data V10.0 installed
Reason for change	Damage code added

Complaint

Customer may state that the wrong curve direction arrow is shown in the instrument cluster (driver) display.

Cause

In navigation map data V10.0 released Q4 2021, some curve sections are partially turned. Therefore, in a right-hand curve, a left-hand direction arrow is sometimes shown or vice versa.

Remedy

In the event of a customer complaint, V9.1 of NTG7 map data can be installed. This map data version is available via Download Manager.

In Q2 2022 an updated map data version will be released (V11.0).

Note: Do not replace any parts for this complaint

Symptoms
Communication/information > Information display > Displays > Multifunction display > Multifunction display, menu > Faulty display
Communication/information > Assistance and warning systems > Traffic Sign Assist > Implausible display

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			540VM	540VM: Function of route-based speed adaptation of Fa control unit