



Volvo Chassis - SNV 20-005 - HD Disc Brake Rotor Upgrade



For more information refer to [SNV 20 - 005 - HD Disc Brake Rotor Upgrade](#).



Tags

[rotor](#)

[disk brakes](#)

[k17200143](#)

[volvo](#)

Related links and attachments

[SNV20-005 HD Disc Brake Rotor Upgrade](#)



Feedback

[Give feedback](#)

to help improve the content of this article



Service News

To: General Managers
Service Managers
Service Technicians
Warranty Managers

Region: U.S.
 CAN

Bulletin: SNV20-005
Date: April 20, 2020
Valid to: N/A
Action Required? Yes No

From: Elizabeth Jolin – Director, Reliability
Subject: HD Disc Brake Rotor Upgrade – Proprietary Disc Brakes

Since January 4th, 2016 a standard duty rotor has been used in certain applications on the VN and VHD.

On April 19th, 2020 a new HD style rotor was introduced to replace the standard duty style rotor.

When replacing a standard rotor with an HD rotor, always replace them in pairs to avoid performance issues such as brake imbalance and/or pulling issues in the braking system.

23887166 HD rotor kit replaces: 21856631 / 22024041 standard kits.

23817078 hub with HD rotor kit replaces: 22757126 / 23156036 / 23720127 Hub with standard rotor kit.

23817064 hub with HD rotor kit replaces: 22757125 / 23156035 / 23720125 Hub with standard rotor kit.

23817093 hub with HD rotor kit replaces: 22757130 / 23156038 / 23720130 Hub with standard rotor kit.

23817088 hub with HD rotor kit replaces: 22757127 / 23156037 / 23720128 Hub with standard rotor kit.

23816957 hub with HD rotor kit replaces: 22755583 / 23156021 / 23720119 Hub with standard rotor kit.

23816953 hub with HD rotor kit replaces: 22755582 / 23155932 / 23720117 Hub with standard rotor kit.

23817013 hub with HD rotor kit replaces: 22755585 / 23156025 / 23720122 Hub with standard rotor kit.

23816978 hub with HD rotor kit replaces: 22755584 / 23156024 / 23720121 Hub with standard rotor kit.

When only replacing the rotor portion of the hub, always replace both rotors.