



Mack Chassis - MP7 And MP8 - Rear Main Crankshaft Seal Replacement - New Part, New Installation And Removal Tools



> Internal Content

Operation [2167-03-03-01 Crankshaft Seal, Replacement \(Rear\)](#) can be found under the Service tab in Impact and contains information for the current tools and procedure.

NOTE: Searching for the Operation using the VIN may lead to instructions for the old tools. Select the Model and enter the Operation ID in the "Search By" field.

Search **Leave blank**

Chassis series Chassis No.

VIN

CXU

Function group

Info type
All Service Information

Clear Search

Additional search values

Search by:
ID/Operation

2167-03-03-01

Service Search - Model CXU

Fgrp	Title	Info type	ID/Operation
216	Crankshaft Seal, Replacement (Rear), Transmission And Clutch Removal	Repair	2167-03-03-01

Showing 1 to 1 of 1 entries

200 Entries

Previous Next

Select the correct model

Make sure "ID/Operation" is selected

Enter Operation ID

Click on the operation and select the appropriate engine size and transmission type with the most recent revision date from the selection screen that opens:

Crankshaft Seal, Replacement (Rear). Transmission And Clutch Removal

Description	ID	Date
CXU, ENG-VE13, HYDRTRAN		11/23/2017
CXU, ENG-VE11, HYDRTRAN		11/23/2017
CXU, ENG-VE11, MECHTRAN		11/23/2017
CXU, ENG-VE13, MECHTRAN		11/23/2017
CXU, ENG-VE13, EM-EU5		01/25/2011
CXU, ENG-VE11, EM-USA07 CXU, ENG-VE11, EM-USA10 CXU, ENG-VE11, EM-USA14		08/09/2012

Allison

mDrive and Eaton

Last Updated



There are several hits on the title.
Choose one of the above.



 Tags [mack](#)

Related links and attachments

No links or attachments available

Feedback

[Give feedback](#)

to help improve the content of this article