

## Safety Recall and Service Campaign - Technician Certification Requirements

Posted 4/14/2022

## **IMPORTANT:**

Refer to the following matrix to determine the technician certification requirements for each specific Safety Recall or Service Campaign. Special Courses and Additional Requirements are noted in the two columns on the far right.

Refer to the Dealer Letter of the specific Safety Recall or Service Campaign for more information.

			Certification Level Requirements														
Safety Recall or Service	Doscription	Poguirod Courses			Certi	ified				Ехре	ert					Special	Additional Requirements
Campaign	Description	Required Courses	Maint										Mast	MDT	Mast MDT	Courses	Additional Requirements
			E	EG	DT	CH	EL	EG	DT	СН	I EL	HY				courses	
18(-7711)07	Certain 2021 Model Year Highlander Vehicles Sealant for a Seam near the Fuel Inlet	Т623															
I ( \P // I F ( ) /	Certain 2018 Model Year Camry & Certain 2018 Model Year Camry Hybrid Coverage for Steering Intermediate Shaft	T453															
\$\$C 221CD4	Certain 2021 Model Year Mirai Vehicles Software Update for the EV Control Computer	Т623															
	Certain 2021 Model Year C-HR, RAV4 Prime, Tundra Certain 2021-2022 Model Year 4Runner, Highlander, Highlander HV, Prius Prime, Sequoia, Tacoma Certain 2022 Prius Data Communication Module (DCM) Reprogramming	Т623															
Safety Recall 22TA02	Certain 2021 Model Year C-HR Vehicles Pre-Collision System (PCS) Inoperative without Warning Indicator	T623															
Equipment Recall 21TH01	Certain 2007-2021 Model Year Tundra Vehicles Certain 2008-2022 Model Year Sequoia Vehicles Potentially Defective Power Steering Gear Assemblies	T453															
Safety Recall 21TA10	Limited Service Campaign 21TD02 (Remedy Notice), Certain 2021 Model Year Tacoma Vehicles, Additional Remote Keyless Entry Key	T453															
CSP 21TE04	Certain 2017-2018 Model Year Avalon Hybrid - Certain 2017 Model Year Camry Hybrid - Coverage for Brake Booster and Brake Booster Pump Assemblies	T553 / T071															
Safety Recall 21TA08	Certain 2022 Model Year Sienna Vehicles Second-Row Outboard Seat Belts Could Tear in a Crash	T623															
Safety Recall 21TA05	Certain 2019 - 2020 Model Year Yaris Sedan Certain 2020 Model Year Yaris Hatchback & Yaris R Vehicle May Stall During Driving at Higher Speeds	Т623															
	Certain 2016 Model Year Avalon Hybrid, Certain 2015-2016 Model Year Camry Hybrid, Certain 2011-2013 Model Year Highlander Hybrid, Coverage for Brake Booster and Brake Booster Pump Assemblies	T553 / T071															
Consumer Advisory 21TG01	Certain 2013-2018 Model Year RAV4, 12-Volt Battery Size and Installation Inspection	T623															
	Certain 2022 Model Year Prius and Prius Prime Vehicles, Vehicle May Lose Motive Power While Driving	T623															
SSC 21TC02	Certain 2021 Model Year Supra Vehicles, Improper Programming in a 21V Battery Management System	TIN519B															
Safety Recall 21TA01	Certain 2009 – 2015 Model Year Venza Vehicles Non-Deployment of Side and Curtain Shield Airbags May Occur	Т623															
SSC 21TC06	SPECIAL SERVICE CAMPAIGN 21TC06 (Remedy Notice) - Certain 2021 Model Year Prius - Pre-Collision System Software Update	T623															
Safety Recall 21TA03	Certain 2018-2019 Model Year 86 (Remedy Notice) -Vehicle May Stall if Low-Pressure Fuel Pump Becomes Inoperative	T623															
LSC 21TD02	Limited Service Campaign 21TD02 (Remedy Notice), Certain 2021 Model Year Tacoma Vehicles, Additional Remote Keyless Entry Key	T623															
Safety Recall 21TA04	Certain 2020-2021 Model Year Supra; Potential Increased Braking Distance	TIN519B															

	<del></del>					Ce	ertifica	ation	Level	Requ	irem	ents					I
Safety Recall or Service	Description	Required Courses			Cer	tified				Ex	pert	•				Special	Additional Requirements
Campaign		nequired courses	Maint	FG	DT	СН	FI	F	G D	-	СН	EL	НV	Mast	MDT	Courses	/ wantional nequilibrium
LSC 21TD03	Certain 2016-2019 Model Year Double Cab Tacoma Vehicles, Center High-Mounted Stop Lamp Assembly - Water Leak	T623		EG	DI	СП			.0 0		СП	CL	ПТ				
SSC 21TC05	Certain 2020-2021 Model Year Highlander; Programming Adjustment for Low Fuel Light	Т623															
SSC 21TC03	Certain 2017-2019 Model Year Highlander Hybrid, 2018-2020 Model Year Camry Hybrid, 2019 Model Year Avalon Hybrid, 2019 Model Year Rav4; Low-Pressure Fuel Pump	T623															
SSC 21TC04	SPECIAL SERVICE CAMPAIGN - 21TC04 - Certain 2021 Model Year C-HR - Incorrect Programming for Rear Seat Belt Reminder Indicator	T623															
CSP 20TE06	CUSTOMER SUPPORT PROGRAM 20TE06 - Certain 2021 Model Year RAV4 HV - Coverage for Vehicle Refueling Performance	T623															
CSP 20TE05	CUSTOMER SUPPORT PROGRAM 20TE05 - Certain 2020 Model Year RAV4 HV - Coverage for Vehicle Refueling Performance	T623															
CSP 20TE04	CUSTOMER SUPPORT PROGRAM 20TE04 - Certain 2019 - 2020 Model Year RAV4 HV - Coverage for Vehicle Refueling Performance	T623															
Safety Recall 20TA02	Certain 2014 FJ Cruiser; 2014-2015 4Runner, Landcruiser; 2017-2020 Sienna, Tacoma; 2018-2020 Avalon, Corolla, Camry, Tundra; 2019-2020 RAV4; 2019 Corolla Hatchback; 2018-2019 Sequoia, Highlander, Landcruiser, 4Runner; Vehicle May Stall During Driving at Higher Speed	T623															
CSP 21TE01	Certain 2012-2014 Model Year Prius C - Coverage for Brake Booster and Brake Booster Pump	T553 / T071															
Safety Recall 20TA16	Certain 2020-2021 Model Year Supra,Potential Fuel Tank Leak							~	/ /	<i>'</i>	✓	✓	✓	✓	✓	TIN519B	
Safety Recall 20TA17	Certain 2020 Model Year Avalon, RAV4, RAV4 Hybrid, Certain 2020 - 2021 Model Year Avalon Hybrid, Steering Column Issue May Affect Airbag Performance					<b>✓</b>		~		,	✓	✓	✓	✓	<b>✓</b>		
CSP 20TE08	Certain 2018 Model Year Prius c Vehicles; Coverage for Specific Cracks in the Tail Lamps Potentially Allowing Water Intrusion			✓	✓	✓	✓		/ /	,	<b>√</b>	✓	✓	✓	<b>✓</b>		
Safety Recall 20TA15	Certain 2021 Model Year RAV4 Prime; Headlamp Beam Could be Improperly Adjusted Horizontally			<b>✓</b>	✓	✓	✓	· •	✓ <b>✓</b>	,	<b>✓</b>	✓	✓	✓	✓		
CSP 20TE03	Certain 2019 – 2020 Model Year RAV4; Adventure and Limited grade AWD only, Coverage for Front Transfer Case Electro-Magnetic Clutch				~				~					✓	✓		
Safety Recall 20TA14	Certain 2020 Model Year Highlander, Highlander HV; Potential Improper Deployment of Seat Mounted Side Air Bag			<b>✓</b>	✓	✓	✓	•	✓ <b>✓</b>	,	<b>√</b>	✓	✓	✓	✓		
CSP 20TE10	Certain 2013-2015 Prius; 2014-2017 Prius V; Hybrid System Software Update Extension of Coverage to the Intelligent Power Module (IPM)												✓	✓	✓		
CSP 20TE07	Certain 2012-2014 Model Year Prius V; Coverage for Brake Booster and Brake Booster Pump Assemblies												<b>✓</b>	✓	✓		
SSC 20TC03	Certain 2019 Model Year Yaris Sedan; Engine Control Module Reprogram			✓	✓	✓	✓	~	<b>√</b> ✓	′	✓	✓	✓	✓	✓		
Safety Recall 20TA13	Certain 2020 Model Year Supra; Headlamp Adjustment Plugs Installed in Incorrect Locations			✓	✓	✓	✓	•	/ /	,	✓	✓	✓	✓	✓		
Safety Recall 20TA01	Certain 1997-1998 Model Year Supra; 1998-1999 Model Year Celica; 1998-2000 Model Year RAV4; 1998-1999 Model Year RAV4 EV Airbag May Not Deploy Properly or Airbag Inflator May Rupture						<b>✓</b>	· •		,	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	<b>√</b>	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall 20TA08	Certain 2019-2020 Rav4; 2019-2020 Rav4 HV; Potential Loss of Vehicle Control due to Front Lower Suspension Arm Separation					<b>✓</b>		·	/ /	,	<b>✓</b>	✓	✓	<b>√</b>	<b>✓</b>		
Safety Recall 20TA12	Certain 2018-2020 Tundra Front Turn Signal Brightness						✓		/ /		<b>√</b>	✓	✓	✓	✓		
Safety Recall 20TA11	Certain 2019-2020 Rav4; 2020 Rav4 HV Potential Loss of Power Steering Assist					✓				工	✓			<b>√</b>	<b>√</b>		
Safety Recall 20TA10 Safety Recall 20TA04	Certain 2013-2015 Prius; 2014-2017 Prius V; Hybrid System Software Update  Certain 2020 Avalon HV, Camry, Camry HV; 2019-2020 RAV4, RAV4 HV; Certain Engine			<b> </b>				<del> </del>	✓	,	<b>✓</b>	✓ ·	✓ ✓	<b>✓</b>	<b>✓</b>		
	Blocks Can Cause Engine Failure Leading to Engine Stall (non-hybrid) and/or Fire Risk								/ /		<i>'</i>		./		, 		
Safety Recall 20TA07 SSC 20TC01	Certain 2020 Corolla Hatchback; Backup Lamps May Become Inoperative  Certain 2012 Tacoma; Air Injection Pumps and Air Switching Valves			<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	\ \ \ \ \ \	·	_	<u>✓</u>	<b>→</b>	<b>v</b> ✓	<b>▼</b>	<b>▼</b>		
Safety Recall 20TA05	Certain 2011-2012 Corolla , Incomplete or Nondeployment of Airbags and/or Seat Belt Pretensioners May Occur											<b>√</b>	✓	✓	<b>✓</b>		
Safety Recall 20TA06	Certain 2020 Highlander, Potential Vehicle Stall While Driving			✓	✓	✓	✓	~	/ /		<b>√</b>	✓	✓	✓	✓		
LSC 20TD01	Certain 2012-2019 Sequoia, Potentially Incorrect Carpet Floor Mats			✓	✓	✓	✓	· •	✓ <u> </u>		✓	✓	<b>√</b>	✓	✓		
Safety Recall 20TA03	Certain 2011-2019 Corolla, 2012-2018 Avalon, 2013-2018 Avalon HV, 2011-2013 Matrix Incomplete or Nondeployment of Airbags and/or Seat Belt Pretensioners May Occur											<b>✓</b>	✓	✓	✓		
Safety Recall 19TA20	Certain 2020 Supra; Headlamp(s) May Become Inoperative							~	/ /		✓	✓	✓	✓	✓	TIN519B	
Safety Recall 20TA04	Certain 2020 Avalon HV, 2020 Camry, Camry HV, 2019-2020 Rav4, RAV 4 HV; Certain Engine Blocks Can Cause Engine Failure Leading to Engine Stall (non-hybrid) and/or Fire Risk	T151															

						Cer	tificat	ion Le	vel Re	quiren	nents					Ī
Safety Recall or Service	Description	Poguired Courses			Cert	ified				Exper					Special	Additional Boquiroments
Campaign	Description	Required Courses	Maint										Mast	MDT	Courses	Additional Requirements
				EG	DT	CH	EL	EG	DT	СН	EL	HY				
Safety Recall 19TA22	Certain 2020 Corolla, Corolla HV, 2019-2020 C-HR; Certain Rear Seat Belt Lock(s) May			✓	✓	✓	✓	✓	✓	✓	✓	✓	$\checkmark$	✓		
SSC 19TC04	Become Inoperative Certain 2017-2019 Highlander HV; Oil Cooler Pipe			<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>✓</b>		
Safety Recall 19TA21	Certain 2019 Prius; Combination Meter Display May Become Inoperative			<b>✓</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>		
SSC 19TC06	Certain 2020 Camry, Avalon; Engine ECU Reprogram			<b>√</b>	<b>√</b>	<b>√</b>	✓	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	✓	✓	<b>√</b>		
				./	<b>√</b>	<b>✓</b>	1	<b>✓</b>	./	<b>√</b>	./	./	./	./	SCK0D	
LSC KOD	Certain 2011-2017 Tacoma Frame Corrosion Resistant Compound (CRC) Application			ľ	v			L v	ľ	v	· ·			<b>V</b>	TIR019A	
Safety (Noncompliance) Recall 19TA19	Certain 2020 Supra Back Up Camera Display - Brightness and Contrast Settings			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall KOL	Certain 2020 Corolla Hybrid, 2019 Rav4, 2019-2020 Prius Prime, 2019 Prius; Potential Loss of Power Brake Assist					✓				✓			✓	✓		
LCC VOD / CCD 10TE12	Certain 2013-2019 4Runner, 2011-2017 Land Cruiser, 2013-2017 Prius, 2012-2017 Prius			./	<b>√</b>	<b>√</b>	./	<b>✓</b>	./	<b>√</b>	<b>1</b>	./	./	<b>/</b>		
LSC KOP / CSP 19TE12	V, 2016-2017 Mirai Safety Connect System - Vehicle Location Inaccurate			v	· ·	L v	· ·	, v	ľ	<b>V</b>	, v	<b>V</b>		V		
Safety Recall KOQ	Certain 2003-2008 Corolla, 2005-2008 Matrix Passenger Airbag May Not Inflate Properly						✓	✓	<b>✓</b>	<b>✓</b>	~	<b>✓</b>	✓	<b>✓</b>	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall KOK	Certain 2018-2019 Prius C, Potential Loss of Motive Power While Driving											✓	✓	✓		
Safety (Noncompliance) Recall KON	Certain 2019 Rav4, 2019 Rav4 HV, Backup Camera Display May Not Operate			<b>✓</b>	✓	✓	<b>✓</b>	✓	✓	<b>✓</b>	✓	✓	✓	<b>✓</b>		
Safety (Noncompliance) Recall KOM	Certain 2019 Camry, Passenger Front and Knee Airbags May Not Deploy as Designed			<b>✓</b>	✓	✓	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>		
Safety Recall J05	Certain 2008-2019 Landcruiser, Passenger Airbags Could Deactivate			<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>		
·	Certain 2019 Sienna Potential Unintended or Non-deployment of Passenger Side Front								†							
Safety Recall KOG	Seat and Curtain Shield Airbags			<b>✓</b>	✓	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>		
Safety Recall K0F	Certain 2015-2017 Yaris, Front Seat Side and Curtain Shield Airbags May Not Deploy as Intended			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
SSC KOB	Certain 2018-2019 Tacoma, Tundra Millimeter Wave Radar Sensor			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall J07	Certain 2019 Corolla Hatchback Potential Loss of Power While Driving				✓				✓				✓	✓		
SSC KOA	Certain 2018 Tundra, Sequoia, Camry, Sienna Engine ECU Software Update			<b>✓</b>	<b>√</b>	<b>√</b>	✓	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	✓	✓	✓		
Safety (Noncompliance) Recall KOI	Certain 2019 Avalon and Camry HV Fuel Filler Pipe			<b>✓</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>		
Safety Recall JS5	Certain 2008-2019 Landcruiser, Passenger Airbags Could Deactivate			<b>✓</b>	<b>√</b>	<b>✓</b>	✓	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>		
Safety Recall JOV	Certain 2010-2014 Prius, 2012-2014 Prius V Hybrid System Software Update											✓	✓	<b>√</b>		
Safety Recall J06	Certain 2018-2019 Tacoma Brake Master Cylinder Replacement					<b>√</b>				<b>√</b>			✓	<b>√</b>		
Safety Recall JOW	Certain 2003-2006 Scion xA Center Airbag ECU Replacement						✓				✓		✓	✓		
Safety (Noncompliance) Recall J08	Certain 2019 Tundra Weight Label Replacement			<b>✓</b>	✓	✓	✓	<b>✓</b>	✓	✓	✓	✓	✓	✓		
Safety Recall J02	Certain 2013 FR-S Valve Spring Replacement							<b>√</b>					✓	<b>√</b>		
SSC JOU	Certain 2008-2015 Scion xB, 2011-2016 Scion tC TRD Brake Kit					✓				✓			✓	✓		
SSC JOR	Certain 2018 Camry, Camry Hybrid, 2016-2018 Prius, 2017-2018 Prius Prime Intelligent Clearance Sonar (ICS) System Reprogram			<b>✓</b>	✓	✓	<b>√</b>	✓	✓	<b>✓</b>	✓	<b>√</b>	✓	<b>✓</b>		
Safety (Noncompliance) Recall JOZ	Certain 2018-2019 Tundra Load Carrying Capacity Modification Label			<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>		
Safety Recall JOY	Certain 2019 C-HR Rear Axle Hub Bearing Bolt					✓				✓			✓	<b>✓</b>		
Safety Recall JOX	Certain 2018-2019 Tundra, Sequoia; 2019 Avalon & Avalon HV SRS Sensor Software Update			<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	✓	<b>✓</b>		
Safety Recall JOT	Certain 2016-2018 Prius Engine Wire Harness											<b>√</b>	✓	<b>√</b>		
Safety Recall JOS	Certain 2012 Avalon Front Seat Belt Buckle Inspection and Replacement			<b>√</b>	✓	<b>√</b>	✓	✓	✓	<b>√</b>	<b>√</b>	✓	✓	✓		
SSC JON	Certain 2016-2017 Tacoma Blower Motor Replacement			✓	<b>√</b>	✓	✓	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>		
SSC JSD	Certain 2014-2017 Corolla, 2017 Corolla iM, 2016 Scion iM Software Update for CVT				✓			✓	✓	✓	✓	✓	✓	✓		
Safety Recall JOM	Certain 2018 Camry Oversized Pistons							<b>√</b>					✓	<b>√</b>		
Safety Recall JOK	Certain 2017 Sienna and Tacoma, 2018 Camry and Highlander Vacuum Pump			<b>√</b>				<b>√</b>					<b>√</b>	<b>√</b>		
Safety Recall JOF	Certain 2016 Prius Airbag Sensor				-	/	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>		
Safety Recall JOG Safety Recall JOJ	Certain 2018 Camry Fuel Delivery Pipe  Certain 2018 Sienna Wheel Replacement		<b>✓</b>	✓	✓ ✓	✓ ✓	✓ ✓	✓ ✓	✓ ✓	✓	✓ ✓	✓ ✓	<b>✓</b>	✓ ✓	SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of
Cafata Danali (O)	Cortain 2017 Tundra Book Soct Law Tarries			<b>✓</b>	<b>✓</b>	<b>✓</b>		<b>/</b>	<b>✓</b>	<b>√</b>	<b>1</b>	<b>1</b>	./	<b>√</b>		SC19A
Safety Recall JOI Safety (Noncompliance) Recall	Certain 2017 Tundra Rear Seat Low Torque			<b>- '</b>	<b>– *</b>	<b>– '</b>	<b>'</b>	<b>  '</b>	<b>, ,</b>	<b>,</b>	<b>- '</b>	<b>v</b>	<b>v</b>	'		
JOH	Certain 2018 Tundra and Sequoia Software Update for Vehicle Stability Control System			✓	✓	✓	<b>✓</b>	✓	✓	✓	✓	✓	✓	✓		

			<u> </u>			Cei	rtificat	tion Le	vel Re	quirer	ments					
Safety Recall or Service	Description	Required Courses			Cer	tified				Exper					Special	Additional Requirements
Campaign	Description	Required Courses	Maint	- FC	DT	CII		FC	DT	CII		LIV	Mast	MDT	Courses	Additional Nequirements
Safety Recall JOA,JOB,JOC	Certain 2003-2010 Matrix, 2003-2013 Corolla, 2003-2006 Tundra, 2002-2007 Sequoia, 2010-2016 4Runner, 2004-2005 Rav4, 2011-2013 Sienna, 2008-2012 xB, 2007-2012 Yaris Sedan, 2007-2011 Yaris Hatchback passenger airbag module			EG	DT	СН	EL ✓	₽G	DT ✓	CH ✓	EL ✓	HY ✓	<b>√</b>	<b>✓</b>	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall G04 Phase 2	Certain 2011-2016 Sienna Power Sliding Door Mobility Vehicle			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
SSC H0X	Certain 2016-2017 Mirai EV Control ECU Software Update			<b>✓</b>	✓	<b>✓</b>	✓	<b>√</b>	✓	✓	✓	✓	✓	✓		
Safety Recall HOR	Certain 2012-2015 Prius PHV Electric Vehicle Fuse Fracture											✓	✓	✓		
Safety (Noncompliance) Recall	Certain 2017 Sienna and Tacoma, 2017-2018 4Runner and Tundra, 2018 Highlander and			<b>✓</b>	✓	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>	✓	✓	✓	<b>✓</b>		
HOZ SSC HOY	Rav4 Load Carrying Capacity Modification Label			<b>✓</b>	<b>✓</b>	<b>✓</b>	./	<b>✓</b>	-/	<b>/</b>	-/	-/	-/	<b>/</b>		
Safety Recall HOV	Certain 2018 Tundra and Sequoia Center Air Bag Software Update 2005-2007 and 2009-2010 Sienna Shift Lock Solenoid Assembly			<b>✓</b>	<b>∀</b>	<b>→</b>	<b>✓</b>	<b>▼</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>		
Safety (Noncompliance) Recall HOW	Certain 2018 C-HR Electronic Parking Brake Reflash			<b>✓</b>	✓	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	✓	✓		
LSC H0T	Certain 2018 Camry Rear Wheel Arch Sealer Gap			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall H0U	Certain 2016 Prius Inverter Assembly Replacement											✓	✓	✓		
SSC HOP	Certain 2017 Yaris Instrument Panel Wire Harness					<u> </u>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	✓	<b>√</b>	<b>✓</b>		
LSC HON	Certain 2018 C-HR Rear Bumper Garnish		✓	✓	✓	✓	✓	✓	✓	✓	✓	<b>✓</b>	<b>✓</b>	✓	SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of SC19A
LSC H0J	Certain 2007-2014 FJ Cruiser Fuel Tank			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
LSC HOL	Certain 2018 C-HR Parking Brake Cover		<b>✓</b>	✓	✓	✓	✓	✓	✓	✓	✓	<b>✓</b>	✓	<b>✓</b>	SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of SC19A
Safety Recall HOS	Certain 2008-2016 Landcruiser Driver Airbag Assembly										✓		✓	✓		
LSC H0F	Certain 2005-2010 Tacoma, 2005-2008 Sequoia, and 2007-2008 Tundra CRC Application		<b>✓</b>	<b>✓</b>	<b>√</b>	~	<b>✓</b>	~	~	~	~	~	✓	<b>✓</b>	SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of SC19A
Safety Recall H0H	Certain 2016-2017 Tacoma Crankshaft Position Sensor			✓				✓					✓	✓		
Safety Recall H0M	Certain 2016 Camry and 2016 Avalon CV Axles				✓	<u> </u>			✓				✓	<b>√</b>		
Safety Recall G04 Phase 1	Certain 2011-2016 Sienna Power Sliding Door						✓				✓		✓	✓	SRG04	SRG04 Instructor Led course from the Region
Safety Recall HOK	Certain 2016 Tundra Knee Airbag Bolts			<b>✓</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	✓	<b>✓</b>		
Emission Noncompliance Recall H0I	Certain 2018 C-HR Emission Label Installation			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall H0G	Certain 2016-2017 Tacoma Rear Differential Leak					<b>✓</b>				<b>√</b>			✓	✓		
Safety Recall H0C	Certain 2016-2017 Tundra Bumper Reinforcement Brackets			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
SSC H0E	Certain 2016 -2017 MY Mirai Fuel Cell System Updates			<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>		
SSC HOD SSC GOY	Certain 2016 Scion iA & 2017 Toyota Yaris iA Certification Label Certain 2006-2008 MY RAV4 Muffler Inspection			<b>✓</b>	<b>✓</b>	✓ ✓	<b>V</b>	<b>-</b>	· ·	<b>✓</b>	<b>V</b>	· ·	<b>✓</b>	<b>✓</b>		
LSC GOX	Certain 2016 MY RAV4 & RAV4 HV Power Rear Hatch ECU			<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	· /		Expires November 30, 2019
	Certain 2016 Avalon and Certain 2017 Camry										./		./	-/		,
Safety Recall G05	Incorrect Passenger Knee Airbag Fasteners										, v			<b>,</b>		
LSC G02	Certain 2015-2016 Camry DSS ECU Update			<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>		Expires October 31, 2019
SSC GOZ	Certain 2017 MY Sienna Powertrain ECU Software Update Certain 2003-2006 MY Land Cruiser, 2005-2006 MY Sequoia, 2005-2006 MY Tundra,		<u> </u>	<b>✓</b>	✓	<b>✓</b>	<b>  '</b>	<b>-</b>	<b>*</b>	<b>√</b>	<b>✓</b>	<del>                                     </del>	<b>*</b>	<b>√</b>		
Safety Recall GOC	2004-2006 MY 4Runner SRS ECU										<b>✓</b>		✓	✓		
Safety Recall GOW	Certain 2016 MY Prius Front Passenger Airbag										✓		✓	✓		
Safety Recall G01	Certain 2016 - 2017 MY Prius Parking Brake Cable Clip		<b>✓</b>	<b>✓</b>	<b>√</b>	✓	✓	✓	~	✓	~	<b>✓</b>	<b>√</b>	<b>✓</b>	SC19A	All technicians in staffmaster are eligible to perform this repair with the completion of SC19A
Safety (Noncompliance) Recall G03	2016 MY Highlander Brake Fluid Reservoir Sensor Connector			<b>✓</b>	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall GOP/GOR/HOA	Certain 2006-2011 MY Yaris Hatchback & 2007-2012 MY Yaris Sedan, 2009-2013 Corolla, 2009-2013 MY Matrix, 2008-2015 MY Scion xB, 2010-2016 4Runner, and 2011-2014 Sienna Takata Airbag						<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall FOS	2009-2012 MY RAV 4 & 2012-2014 MY Rav4 EV Ft. Wiper Arm Crank Arm			✓	✓	✓	<b>√</b>	✓	✓	✓	✓	<b>√</b>	✓	✓		
Safety Recall GOU	2010 - 2012 MY Prius & Prius Plug-in Curtain Shield Airbag			<u> </u>							<b>√</b>		<b>√</b>	<b>√</b>		
Safety Recall GOS Safety Recall GOV	2015 MY Yaris Front Strut Bearing Inspection 2006-2011 MY RAV4 Rear Lower Suspension Arm No.1					<b>√</b>				✓ ✓			✓ ✓	✓ ✓	SCG0V SCGOVH	Technicians must also successfully complete SCGOV online and SCGOVH conducted by the Regions.
LSC GOT	Certain 2016 MY Prius Simple Advance Parking Guidance System			<b>✓</b>	<b>√</b>	✓	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	✓	<b>√</b>	✓	<b>✓</b>		negions.
Safety Recall G0M	2015-2016 MY Toyota Prius V Emission Control Information Label			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
LSC GOL	2016 MY Scion iA Spare Tire Pressure Adjustment			✓	✓	✓	<b>√</b>	✓	✓	<b>√</b>	✓	✓	<b>√</b>	✓		

Section Services   Description   Descripti			<u> </u>				Cei	rtificat	ion Le	evel Re	auiren	nents					I
Section   Company   Comp	Safety Recall or Service	Description	Required Courses			Cert					•					Special	Additional Requirements
CORD   2015 For Sear A recipion on and outcome of Social Accordance (Corporation Corporation Corpora	Campaign	Description	Required Courses	Maint			611	ļ <u>-</u> .			011		107	Mast	MDT	•	Additional Nequirements
Marry Private Cold   Content (CES)   Content	TEC CON	2016 MV Scien iA Inspection and Adjustment of Coolant Concentration					1	EL V		_	1		HY	1	1		
Section   Content   Cont					+ •	<del>                                     </del>	+ •	+ •		<b>,</b>	<b> </b>	<b> </b>	•	<del>,</del>	<b>,</b>		
Select product On   Process from the form and followings of and processors from the regist adjusted   V V V V V V V V V V V V V V V V V V	Safety Recall G0J								<b>✓</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>		
Section   Company   Comp	Safety Recall G0I						✓				✓			✓	✓		
Self-ty-Family   Self	Safety Recall G0H				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Select Price of Control Vision (2012) And Price of Designate Selection (1)   Control Vision (2012) 200 And Price of Responsive System (Automated VI V V V V V V V V V V V V V V V V V V	·				<b>/</b>	<b>/</b>	<b>/</b>	<b>/</b>	<b>/</b>	<b>/</b>	<b>/</b>	1	<b>/</b>		<b>/</b>		
Safety Neural Coll   Series	·							· ✓				· ✓	· ✓	<u> </u>	·		
Section   Procession Makes with Improved Section Processing Section   Processing Section	·																
Series   S	Safety Recall G0E				<b>~</b>	<b>✓</b>	<b>✓</b>	<b>_</b>	<b>_</b>	<b>~</b>	<b>~</b>	<b>✓</b>	<b>✓</b>	✓	<b>~</b>		
Comment	Safety Recall F0V	Certain 2013-2015 MY Avalon, Avalon HV Pre-Collision System							<b>✓</b>	✓	✓	<b>✓</b>	<b>✓</b>	✓	✓	SCF0V	
Safety Recall FD		Converter			<b>√</b>	<b>√</b>		<b>✓</b>	<b>✓</b>	<b>✓</b>		<b>✓</b>	<b>√</b>	✓	<b>✓</b>		*If inspection determines the vehicle requires additional electrical repairs, it must be preformed by a technician who is expert or above
Select Normal Foot   Management ECU   Select Normal Highward replaced space software Lipidate for Am soil [A/F] Sensor   Management ECU   Ma	Safety Recall FOT				✓	✓	✓	✓	✓	✓	✓	✓	✓	<b>√</b>	✓		
Series   Monitoring   Series   Series   Monitoring   Series	Safety Recall FOR	Management ECU											✓	✓	<b>✓</b>		
List From   2011 MY Serims and Rever Legislate for Variable Valve Left Control	Safety Recall FOP				✓	<b>√</b>	<b>✓</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	✓	✓	✓	<b>✓</b>		
Safety Recall FOL  2004-2005 MV RNV4 Front Driver Airhag inflator Module  Safety Recall FOL  2015-6MY Scient C Vivinies have Seed Segretion Are  Safety Recall FOL  2015-6MY Scient C Vivinies have Seed Segretion Are  Safety Recall FOL  2014-7015 Model year AVV, 2015 Highlander and Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV HV HV HV Highlander and Highlander HV, and 2015 Camry and Camry HV HV HV HV Highlander Seed Highlander HV, and 2015 Camry and Camry HV	LSC FON				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall FUL   2004-2005 MY REVAIL Frost Univer Arriage Infator Module	LSC FOM	2011 MY Sienna 3rd Row Seat Back Panel Replacement			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall FD    2012-2014 MVR MAVE (2015 Highlander and Highlander HV, and 2015 Carriny and Carry Wehicles   Solitive Recall FO    2012-2014 MVR MAVE (Extric (EVEY Truction Motor Assembly   Safety Recall FO    2012-2014 MVR MAVE (Extric (EVEY Truction Motor Assembly   Safety Recall FO    2012-2014 MVR MAVE (Extric (EVEY Truction Motor Assembly   Safety Recall FO    2012-2014 MVR MAVE (Extric (EVEY Truction Motor Assembly   Safety Recall FO    2012-2014 MVR MAVE (Extric (EVEY Truction Motor Assembly   Safety Recall FO    2012-2014 MVR MAVE (Extric (EVEY EVEY Truction Motor Assembly   Safety Recall FO    2012-2014 MVR MAVE (EXTRIC (EVEY EVEY Truction Motor Assembly   Safety Recall FO    2012-2014 MVR MAVE (EXTRIC (EVEY EVEY EXTRICAL EXT	Safety Recall F0L	2004-2005 MY RAV4 Front Driver Airbag Inflator Module						✓	~	<b>✓</b>	<b>✓</b>	<b>✓</b>	<	✓	✓	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall E01   2012 - 2014 MY RAVE Bletric [EV] EV Traction Motor Assembly	Safety Recall FOK	2015 MY Scion tC Vehicles Rear Suspension Arm					<b>√</b>				<b>√</b>			✓	<b>✓</b>		
Safety Recall FOH   2012-2014 MYRAV4 Electric (EV) FV Traction Motor Assembly   V	·	2014-2015 Model Year RAV4, 2015 Highlander and Highlander HV, and 2015 Camry and					1				1			<u> </u>	1		
Safety Recall FOH   2012 - 2015 MV yrars Hatchback Headliner Replacement	·	,					•				•			•			
Safety Recall FQC  Certain 2014 Model Year Avaion. Avaion Hybrid Carmy, and Carmy Hybrid Vehicles Driver Side Front Suspension Lower Arm  Safety Recall EQC  Safety Recall EQC  Certain 2015 Model Year Tundra and Sequola Vehicles FCM Software Update  Safety Recall EQC  Safety Recall EQC  Certain 2012-2004 Model Year Tundra and Sequola Vehicles Fornt Passenger Ariseg inflator Module  Safety Recall EQC  Certain 2012-2005 Model Year Avaion. Avaion Hybrid Vehicles Driver Side Front Suspension Lower Arm  Safety Recall EQC  Certain 2014 Model Year Avaion. Avaion Hybrid Vehicles Driver Side Front Suspension Lower Arm  Safety Recall EQC  Certain 2014 Model Year Avaion. Avaion Hybrid Vehicles Driver Side Front Suspension Lower Arm  Safety Recall EQC  Certain 2014 Model Year Avaion. Avaion Hybrid Vehicles Driver Side Front Suspension Lower Arm  Safety Recall EQC  Certain 2014 Model Year Avaion. Avaion Hybrid Vehicles Driver Side Front Suspension Lower Arm  Safety Recall EQC  Certain 2014 Model Year Avaion. Avaion Hybrid Vehicles Driver Side Front Suspension Lower Arm  Safety Recall EQC  Certain 2014 Model Year Avaion. Avaion Hybrid Vehicles EQM Software Update  Certain 2014 Model Year Avaion. Avaion Hybrid Vehicles EQUipped with 2SR FE Engine - Potential Foul Delivery Pipe Leak  Safety Recall EQC  Certain 2014 Model Year Tundra and Sienna Wehicles Equipped with 2SR FE Engine - Potential Foul Delivery Pipe Leak  Safety Recall EQC  Safety Recall EQC  Certain 2014 Model Year Tundra Delivery Avaion Service Sequence of Avaion Service Sequence Service Ser	<b>'</b>	` '											<b>√</b>	<b>√</b>	· ·	012D	
Safety Recall FOF Safety Recal	,	2012 - 2015 MY Yaris Hatchback Headliner Replacement			· ·	· ·	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	<b>'</b>	•	<b>'</b>	· ·	<b>,</b> ,		
Safety Recall F0E Safety Recal	Safety Recall FOG				<b>√</b>	✓	<b>√</b>	✓	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	✓	<b>√</b>	<b>√</b>		
Safety Recall EU   Steering Intermediate Shaft Assembly	Safety Recall F0F	Rear Axle Hub Bearing Torque Confirmation					✓				✓			✓	<b>√</b>		
Safety Recall EO4 — High Absolute Humidity  Safety Recall EO2 — Certain 2014 Model Year Corolla, Corolla Matrix, and Tundra Vehicles Front Absolute Humidity  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2012-2014 Model Year Carmy Vehicles UT60 ATM ECM Software Update  Safety Recall EO2 — Certain 2014 My Avalon, Carmy, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine — Potential Fuel Delivery Pipe Leak  Safety Recall EO2 — Certain 2014 My Avalon, Carmy, Highlander and Sienna Vehicles Curtain Shield  Safety Recall EO2 — Certain 2014 My Avalon, Carmy, Highlander and Sienna Vehicles Curtain Shield  Safety Recall EO2 — Certain 2014 My Avalon, Carmy, Highlander and Sienna Vehicles Curtain Shield  Safety Recall EO2 — Certain 2014 My Avalon, Carmy, Highlander and Sienna Vehicles Curtain Shield  Safety Recall EO2 — Certain 2014 My Avalon, Carmy, Highlander and Sienna Vehicles Curtain Shield  Safety Recall EO2 — Certain 2014 My Avalon, Carmy, Highlander and Sienna Vehicles Curtain Shield  Safety Recall EO2 — Certain 2014 My Avalon, Carmy, Highlander and Sienna Vehicles Curtain Shield  Safety Recall EO2 — C	Safety Recall F0E						✓				✓			✓	✓		
FDC Occupant Classification System (OCS) Sensor  LSC FDB Certain 2012-2014 Model Year Tundra and Sequola Vehicles  LSC FDA Certain 2012-2014 Model Year Avalon, Avalon Hybrid, Carry, and Carry Hybrid Vehicles  Driver Side Front Suspension Lower Arm  Safety Recall E05 Driver Side Front Suspension Lower Arm  Certain 2012-2014 Model Year Carry Vehicles Uniform Mediting Passenger Airbag Inflator Module  LSC E03 Certain 2012-2014 Model Year Carry Vehicles Uniform Rear Leaf Spring Replacement  Safety Recall E02 Certain 2005 - 2011 Model Year Tacoma Rear Leaf Spring Replacement  Safety Recall E01 Certain 2014 My Avalon, Carry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine — Potential Fuel Delivery Pipe Leak  Safety Recall E02 Certain 2014 My Avalon, Carry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine — Potential Fuel Delivery Pipe Leak  Safety Recall E02 Certain 2014 My Avalon, Carry, Highlander and Sienna Vehicles Curtain Shield Agriculture and Scienna Vehicles Curtain Shield Agriculture and Service Certain South Read Scienna Vehicles Curtain Shield Agriculture and Service Certain South Read Scienna Vehicles Curtain Shield Agriculture and Service Certain South Read Scienna Vehicles Curtain Shield Agriculture and Service Certain South Read Scienna Vehicles Curtain Shield Agriculture and Service Certain South Read Scienna Vehicles Curtain Shield Agriculture and Service Certain South Read Scienna Vehicles Curtain Shield Agriculture and Service Certain South Read Scienna Vehicles Curtain Shield Agriculture and Service Certain South Read Scienna Vehicles Curtain Shield Agriculture Scienna Vehicles Curtain Scienna Vehicles Curtain Shield Agriculture Sc	Safety Recall F0D							✓				✓		✓	✓		
LSC FOB  Certain 2012-2014 Model Year Tundra and Sequoia Vehicles  LSC FOA  Certain 2012-2014 Model Year Tundra and Sequoia Vehicles ECM Software Update  Safety Recall EO7  Certain 2015 MY Sienna Vehicles Second Row Overhead Assist Grips  Certain 2014 Model Year Avalon, Avalon Hybrid, Carnry, and Carnry Hybrid Vehicles  Driver Side Front Suspension Lower Arm  Absolute Humidity  Passenger Airbag Inflator Module  Certain 2012-2014 Model Year Carnry Vehicles U760 ATM ECM Software Update  Safety Recall E02  Certain 2012-2014 Model Year Carnry Vehicles U760 ATM ECM Software Update  Safety Recall E02  Certain 2012-2014 Model Year Tacoma Rear Leaf Spring Replacement  Safety Recall E02  Certain 2014 MY Avalon, Carnry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine — Potential Fuel Delivery Pipe Leak  Certain 2014 Mydel Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag All All Andrea County Recall E02  Safety Recall E02  Safety Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag All All Andrea County Recall E02  Safety Recall E02  Safety Recall E02  Certain 2014 Myd Avalon, Carnry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine — Potential Fuel Delivery Pipe Leak  Safety Recall E02  Safety Recall E02  Safety Recall E03  Safety Recall E04  Safety Recall E05  Safety Recall E06  Safety Recall E07  Safety Recall E07  Safety Recall E08  Safety Recall E08  Safety Recall E08  Safety Recall E09  Certain 2014 Myd Avalon, Carnry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine — Potential Fuel Delivery Pipe Leak  Certain 2014 Myd Avalon, Carnry, Highlander and Sienna Vehicles Curtain Shield Airbag All Recall E07  Safety (Narrows March 2014 Mydel Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag All Recall E07  Safety Recall E07  Safety Recall E08  Safety Recall E08  Safety Recall E08  Safety Recall E09  Safe		•							✓	✓	✓	✓	✓	✓	<b>√</b>		
Safety Recall EO7 Certain 2015 MY Sienna Vehicles Second Row Overhead Assist Grips  Certain 2014 Model Year Avalon, Avalon Hybrid, Carry, and Carry Hybrid Vehicles Driver Side Front Suspension Lower Arm  Safety Recall E04 — High Absolute Humidity Passenger Airbag Inflator Module  Certain 2012-2014 Model Year Corolla, Corolla Matrix, and Tundra Vehicles Front Passenger Airbag Inflator Module  Certain 2012-2014 Model Year Carry Vehicles U760 ATM ECM Software Update  Safety Recall E02 Certain 2012-2014 Model Year Tacoma Rear Leaf Spring Replacement  Safety Recall E02 Certain 2014 MY Avalon, Carry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine — Potential Fuel Delivery Pipe Leak  Safety Recall E02 Certain 2014 Myd Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Alribag  Safety (Monormopliance) Berall  Safety (Monormopliance) Berall  Safety (Monormopliance) Berall  Safety (Monormopliance) Berall												✓		✓	<b>√</b>		
Safety Recall E05  Certain 2014 Model Year Avalon, Avalon Hybrid, Camry, and Camry Hybrid Vehicles Driver Side Front Suspension Lower Arm  Certain 2003 – 2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles Front Absolute Humidity Absolute Humidity  Certain 2003 – 2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles Front Passenger Airbag Inflator Module  Certain 2012-2014 Model Year Camry Vehicles U760 ATM ECM Software Update  Certain 2012-2014 Model Year Tacoma Rear Leaf Spring Replacement  Certain 2014 Mydalon, Camry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine – Potential Fuel Delivery Pipe Leak  Certain 2014 Mydal Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographics Recall E02  Certain 2014 Mydal Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographics Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Micrographiances Recall E02  Certain 2014 Model Year Tundra Double Cab and	LSC F0A	Certain 2012-2014 Model Year Tundra and Sequoia Vehicles ECM Software Update			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety Recall EO5  Certain 2014 Model Year Avalon, Avalon Hybrid, Camry, and Camry Hybrid Vehicles Driver Side Front Suspension Lower Arm  Certain 2003 – 2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles Front Absolute Humidity Absolute Humidity Absolute Humidity  Certain 2012-2014 Model Year Camry Vehicles U760 ATM ECM Software Update  LSC E03  Certain 2012-2014 Model Year Tacoma Rear Leaf Spring Replacement  Certain 2015 - 2011 Model Year Tacoma Rear Leaf Spring Replacement  Safety Recall E01  Certain 2014 MY Avalon, Camry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine – Potential Fuel Delivery Pipe Leak  Certain 2014 MOdel Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance) Recall E02  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag Michagan Safety (Noncompilance)	Safety Recall E07	Certain 2015 MY Sienna Vehicles Second Row Overhead Assist Grips							<b>√</b>	✓	<b>√</b>	✓	<b>√</b>	✓	<b>√</b>		
Absolute Humidity Passenger Airbag Inflator Module  LSC E03 Certain 2012-2014 Model Year Camry Vehicles U760 ATM ECM Software Update  Safety Recall E02 Certain 2005 - 2011 Model Year Tacoma Rear Leaf Spring Replacement  Certain 2014 MY Avalon, Camry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine – Potential Fuel Delivery Pipe Leak  Safety Recall E0Z Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag  Safety (Noncompliance) Recall E0Z		Certain 2014 Model Year Avalon, Avalon Hybrid, Camry, and Camry Hybrid Vehicles					✓				<b>√</b>			✓	✓		
Safety Recall EO2  Certain 2005 - 2011 Model Year Tacoma Rear Leaf Spring Replacement  Safety Recall EO1  Certain 2014 MY Avalon, Carry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine – Potential Fuel Delivery Pipe Leak  Safety Recall EO2  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag  Safety (Noncompliance) Recall  Safety (Noncompliance) Recall	,							<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>✓</b>	✓	✓	SC18A	All technicians that have already taken SC13B do not have to take SC18A
Safety Recall EO2 Certain 2005 - 2011 Model Year Tacoma Rear Leaf Spring Replacement  Safety Recall EO2 Certain 2014 MY Avalon, Camry, Highlander and Sienna Vehicles Equipped with 2GR-FE Engine – Potential Fuel Delivery Pipe Leak  Safety Recall EOZ Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag  Safety (Noncompliance) Recall	LSC E03	Certain 2012-2014 Model Year Camry Vehicles U760 ATM ECM Software Update			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
Safety (Noncompliance) Recall  Engine – Potential Fuel Delivery Pipe Leak  Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield  Airbag  Safety (Noncompliance) Recall	Safety Recall E02						<b>✓</b>				<b>√</b>			✓	<b>✓</b>		Remedy launched for vehicles in Boston, New York, CAT, Cincinnati, Denver, Portland and Chicago regions.
Safety Recall EOZ Airbag  Safety (Noncompliance) Recall	Safety Recall E01				<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>	✓	✓		
Safety (Noncompliance) Recall	Safety Recall EOZ								<b>✓</b>	✓	✓	<b>√</b>	✓	✓	<b>✓</b>		
EOY  Certain 2014 MY FJ Cruiser Trail Teams Ultimate Edition Package Lower Ball Joint Bolt		Certain 2014 MY FJ Cruiser Trail Teams Ultimate Edition Package Lower Ball Joint Bolt					✓				✓			✓	✓		
Safety (Noncompliance) Recall EOX Recommended LT Tires  Certain 2008-2014 MY Tacoma and FJ Cruiser TRD Accessory Wheels and Toyota	Safety (Noncompliance) Recall				~	<b>√</b>	✓	<b>✓</b>	✓	<b>✓</b>	✓	✓	✓	✓	✓		

	T					Cer	rtificat	tion Le	evel Re	quire	nents					I
Safety Recall or Service	Description	Danis d Carre			Cer	tified				Exper					6	1
Campaign	Description	Required Courses	Maint										Mast	MDT	Special	Additional Requirements
				EG	DT	СН	EL	EG	DT	СН	EL	HY			Courses	
Safety (Noncompliance) Recall	Certain 2014 Model Year Sienna Vehicles			<b>/</b>	\ \ \	<b>√</b>	./	<b>✓</b>	./	<b>√</b>	<b>√</b>	./	./	<b>√</b>		
EOW	Transmission Shift Control Cable							•			•	, v	•	•		
LSC EOU	2007-2011 MY Camry Hybrid Vehicles Brake Reservoir Tank Replacement									✓			✓	✓		
Safety Recall EOT	Certain 2014 Model Year Highlander and Highlander HV Passenger Seatbelt Selectable							<b>√</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b> </b>		
Sarety Result 201	Force Limiter – Software Update															
Special Service Campaign ESS	Certain 2004-2011 Model Year Sienna 2WD Vehicles Equipped w/ a Spare Tire -			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
	Excessive Corrosion of the Spare Tire Carrier Cable															
Safety Recall EOS	Certain 2004-2011 Model Year Sienna 2WD Vehicles Equipped w/ a Spare Tire - Excessive Corrosion of the Spare Tire Carrier Cable			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
	2014 Model Year Highlander Vehicles															
Safety Recall EOR	2nd Row Passenger-Side Inboard Seat Track for 60/40 Split Seat			✓	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	✓	✓	<b>✓</b>	<b>√</b>	<b>√</b>	<b>✓</b>		
100 500												,				
LSC EOP	Certain 2014 Model Year Toyota Highlander Hybrid Vehicles Coolant Hose Clearance											<b>v</b>	•	<b>✓</b>		
LSC EON	Certain 2011-2014 Model Year Toyota Sienna						/				<b>√</b>		<b>√</b>	<b>✓</b>		
LJC LUIV	Pre-Collision System (PCS) Driving Support ECU										Ţ					
Safety Recall EOM	09-10 Corolla, 09-10 Matrix, 08-10 Highlander, 09-10 Tacoma, 06-10 Rav4, 06-10 Yaris;						✓				✓		✓	✓		
,	Spiral Cable		<u> </u>	1	<del> </del>	<u> </u>			-	<del> </del>	<u> </u>	<u> </u>				
Safety Recall EOL	06-10 Yaris HB, 07-10 Yaris Sedan, and 08-10 Scion xD; Driver's Seat Track Assembly &			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
	Passenger Track Assembly (3-Door Yaris Only) 2014 MY Avalon, Avalon Hybrid, Highlander, and Sienna Vehicles Safety Connect			1	+	1		1		+	+	<del>                                     </del>				
LSC EOK	System Disabled			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		
	Certain 2013-2014 Model Year Avalon & Avalon HV Driver & Passenger Front Seatback									1				<u> </u>		
LSC EOJ	Board			<b>✓</b>	<b> </b>	✓	<b>✓</b>	✓	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>✓</b>		
Safety (Non-Compliance)	2012 MAY High lander 2nd Devot off Head Coat link and Coat Trade			<b>√</b>	\ \ \	<b>√</b>	1	<b>√</b>		<b>√</b>	1			<b>√</b>		
Recall E0H	2013 MY Highlander 2nd Row Left Hand Seat Inboard Seat Track			v		v	v	<b>V</b>	v	·	<b>V</b>	<b>V</b>	•	v		
Safety Recall EOG	2003-2004 Avalon Supplemental Restraint System (SRS) Electronic Control Module										<b>✓</b>		<b>√</b>	<b> </b>		
•				-												
Safety Recall EOF	2012-2013 MY Tacoma, 2012 RAV4 Brake Actuator Reprogramming							<b>-</b>	<b>-</b>	<b>√</b>	<b>~</b>	<b>V</b>	<b>✓</b>	<b>V</b>		
Safety Recall E0E	2010-2014 Prius Software Update for Motor Generator ECU & Power Management ECU											✓	✓	✓		
Safety (Non-Compliance)			<u> </u>							<u> </u>						
Recall EOC	2014 MY Highlander; 3rd Row Center Seat Belt			<b>✓</b>	<b>✓</b>	✓	<b>✓</b>	✓	<b>✓</b>	✓	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>		
Safety (Non-Compliance)	NAUltiple 2012 2014 NAV Nadela Cost Hootey Assemblies						./				./		./	<b>1</b>		
Recall EOB	Multiple 2013-2014 MY Models Seat Heater Assemblies												•	•		
Safety Recall DSF	03-04 MY Corolla, Matrix, & Tundra and 02-Early 04 MY Sequoia						✓	✓	✓	✓	✓	✓	✓	✓	SC18A	All technicians that have already taken SC13B do not have to take SC18A
	2003-2004 Corolla and Corolla Matrix Supplemental Restraint System (SRS) Electronic															* Your Regional Office may have specific
Safety Recall DSB	Control Module (ECM) Front Passenger Airbag Inflator Module										<b>✓</b>		<b>√</b>	<b> </b>		requirements to perform this remedy.
																Please confirm with them prior to starting
Safety Recall D0U	2013-2014 MY Tacoma 4 Cylinder Valve Spring Replacement							✓	✓				✓	✓		
Safety Recall DOT	2012-2013 Avalon, Camry, Camry HV, and Venza, 2013 Avalon HV HVAC Assembly										✓		✓	✓		
				-	-	<del> </del>		1			1	<del>                                     </del>				
Safety Recall DOS	2013 Avalon & Avalon HV, 2013-2014 Camry & Camry HV, 2014 Corolla Windshield Wiper Switch						✓				✓		✓	✓		
Safety Recall DOR	2004-2005 and 2007-2009 Sienna Shift Lock Solenoid Assembly			<b>✓</b>	<b>✓</b>	<b>√</b>	✓	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>√</b>		
,				1	1	1		1	<b>√</b> **		1	./	./	./	071	**Drivetrain Expert and completion of
LSC DON	2011-2012 HV Highlander HV Rear Driveshaft Assembly Replacement			<u> </u>	<u> </u>	<u> </u>		1	•		1		•		0/1	course 071 Toyota Hybrid System
Safety Recall DOM	2006-2010 MY Highlander HV Intelligent Power Module (IPM) Replacement			<u> </u>	<u> </u>	<u> </u>		1	-		1	<b>✓</b>	✓	✓		
Safety Recall DOL	2005-2011 MY Tacoma Access Cab Vehicles Driver and Front Passenger Seat Belt						✓				✓	1	✓	✓		
Safety Recall DOK	Assemblies 2012 Yaris MY Power Steering Control Module						<b>✓</b>				<b>√</b>	1	<b>✓</b>	<b>✓</b>		
Safety Recall DOH	Safety Recall DOH: 2010 Prius; Brake Booster Pump Assembly (Accumulator)			1	<del>                                     </del>	<b>√</b>				<b>✓</b>	<del>                                     </del>		✓	· ✓		
, -				1	1	1		1		1	1	1				* Vous Pogional Office was been seen
Safety (Non-Compliance) Recall DOG	2007-2013 FJ Cruiser Genuine Toyota Auxiliary Light Kit Accessory															* Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting
Safety Recall D0F	2003-2004 Corolla, Matrix, Tundra and 2002-2004 Sequoia Front Passenger Airbag Inflator Module						<b>✓</b>	~	<b>√</b>	<b>√</b>	~	<b>√</b>	<b>√</b>	<b>✓</b>	SC18A	All technicians that have already taken SC13B do not have to take SC18A

	Description Required C					Cer	tificat	ion Le	vel Re	quiren	nents					
Safety Recall or Service		Required Courses			Cert	tified				Exper	t				Special	Additional Requirements
Campaign	Description	Required Courses	Maint			0				0			Mast	MDT	Courses	Additional Requirements
				EG	DT		EL		DT	СН	EL	HY				* Your Regional Office may have specific
Safety Recall DOC	2007 - 2013 MY FJ Cruiser Access Door Inner Panel			<b>√</b>	✓	<b>√</b>	<b>√</b>	✓	<b>√</b>	✓	✓	<b>√</b>	<b>√</b>	<b>√</b>		requirements to perform this remedy. Please confirm with them prior to starting
Safety Recall DOB	2003-2004 MY Corolla and Corolla Matrix Supplemental Restraint System (SRS) Electronic Control Module (ECM)										<b>✓</b>		<b>✓</b>	<b>✓</b>		* Your Regional Office may have specific requirements to perform this remedy. Please confirm with them prior to starting
Safety Recall COM	Certain 2007-2008 Yaris, 2007-2009 Rav4, 2007-2009 Tundra, 2007-2009 Camry, 2007-2009 Camry HV, 2008-2009 Scion xD, 2008-2009 xB, 2008-2009 Sequoia, 2008 Highlander and Highlander HV, 2009 Corolla, and 2009 Matrix Vehicles Power Window Master Switch (PWMS)			<b>√</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	~	SCC0M2	
LSC 90K	Multiple Models and Model Years 2GR-FE (V6) Engine VVTi Oil Hose			✓				✓					✓	✓		
Warranty Enhancement Program ZF5	Certain 2012 – 2014 Model Year Prius V Extension of Warranty Coverage to the Intelligent Power Module (IPM)											✓	✓	✓		
Warranty Enhancement Program ZF3	Certain 2010-2012 Prius, 2012 Prius V, 2010-2012 Prius Plug-In Sticking Exhaust Gas Recirculation (EGR) Valve			<b>✓</b>				✓					✓	<b>✓</b>		
Warranty Enhancement Program ZE3	Certain 2010 – 2014 Model Year Prius Vehicles Extension of Warranty Coverage to the Intelligent Power Module (IPM)											<b>✓</b>	<b>✓</b>	<b>✓</b>		